

A TOP RATED SHOP
POPLAR GROVE
AIRMOTIVE
NC
1-800-397-8181
poplargroveairmotive.com



The Standard

ENGINE LOG

A31-99-2



Phone: 815.544.2300 800.397.8181 LIMITED AIRCRAFT ENGINE WARRANTY FAX: 815.544.8900

Poplar Grove Airmotive, Inc. (PGA) limits its warranty on the listed engine overhauled by PGA to be free from defects in material and workmanship under normal use and service for a period of two years or 500 hours, whichever occurs first from the completion date of the overhaul. All accessories overhauled by PGA are warranted for 250 hours of operation or one year, whichever event shall occur first.

Any engine, cylinder or component Repair not associated with a major engine overhaul is warranted to be free from defects in material and workmanship for six months.

The obligation of the Company under this warranty is limited to the repair or replacement, at the option of PGA, of any part, component or engine, which, in the opinion of PGA is defective. PGA assumes no obligation for work accomplished at a facility other than PGA unless prior notification is given and the owner receives authority from PGA to proceed. PGA additionally reserves the right to furnish any parts and/or components required. If requested by PGA, owner must return all warranted parts, transportation prepaid, to PGA for examination.

Warranty is not applicable to routine maintenance, inspection or adjustments. Replacement or repair of an engine component or accessory will not be construed to extend the initial warranty period.

This warranty shall not apply to engines, their component parts or accessories which have been improperly installed, adjusted, stored, handled, repaired, altered or operated contrary to current manufacturer's recommendations of FAA Airworthiness Directives, or subjected to misuse, neglect, accident, pre-ignition, detonation, hydrostatic lock or corrosion.

PGA does not warrant accessories, such as factory-remanufactured magnetos, carburetors, starters, etc. supplied by a vendor other than PGA when that vendor has its own warranty.

No express warranties and no implied warranties, whether of merchantability or fitness for any particular use, or otherwise (except to title) other than that expressly set forth above, which is made expressly in lieu of all other warranties, shall apply to products sold by PGA.

This warranty and this PGA's obligation thereunder is in lieu of all other warranties, expressed or implied, including warranties of merchantability and fitness for a particular purpose, and all other obligations or liabilities, including consequential damages or contingent liabilities arising out of the failure of any engine or part to operate properly, and no person is authorized to give any other warranty or to assume any additional obligation on PGA's behalf unless made in writing and signed by an officer of PGA.

Date 5 JUN 2019 Model O-360A1F6D S/N L-19038-36A WO# 1000056

After starting the engine for takeoff power. We insure good air speed operating handbook. into the green arc.

If the engine is normal. We recommend a...

Do not run the engine requires cylinder re to keep the engine

Descend at low c as this will cause t

There is only one such a manner t **be** used in the e not use AD (ash)

Engine Oil Rec
Aero Shell 100
Aero Shell 80
Aero Shell 65
Phillips 20W-50
Phillips 20W-50

Use mineral b

POPLAR GROVE AIRMOTIVE, INC.
CRS YYBR664L
SUGGESTED BREAK-IN PROCEDURES

After starting the engine, ensure a normal warm up, but avoid prolonged ground running. Follow the airframe manufacturer's recommendations for takeoff power. When possible, reduce power to the climb power setting specified in the operator's manual. Establish a shallow climb angle to insure good air speed for proper cooling. Use more cowl flaps than normal or step climb to help in this process. Adjust mixture per aircraft operating handbook. Excessive heat is the primary cause of cylinder bore glazing. Make every effort to keep your operating temperature well into the green arc.

If the engine is normally aspirated (non-turbocharged) it will be necessary to cruise at a low altitude to obtain the required cruise power levels. We recommend a density altitude less than 5,000 feet to allow the engine to develop sufficient cruise power for a good break-in.

Do not run the engine above 75% power in a cruise setting or the probability of glazing cylinder bores is increased. Glazing cylinder bores requires cylinder removal, honing and installing new piston rings. **Poplar Grove Airmotive does not warranty this condition.** Your ability to keep the engine temperature well in the green arc and within a power range of 65% to 75% power will be the key to a successful break in.

Descend at low cruise power while closely monitoring the engine instruments. Avoid long descents at low manifold pressure and rapid descents, as this will cause the engine to cool too rapidly.

There is only one object to be accomplished during the break-in: the stabilization of oil consumption. Record all oil additions and flight hours in such a manner that quart per hour of flight is known. During this portion of the break-in, which could range 25 to 100 hours, mineral oil **must be** used in the engine. Change oil and inspect filter after approximately 10 hours – then 35 hours – then per your normal schedule, however, do not use AD (ashless dispersant) oil until consumption stabilizes.

Engine Oil Recommendation For Piston Ring Seating

Aero Shell 100	SAE 50	Above 60 degrees F
Aero Shell 80	SAE 40	30 degrees – 90 degrees F
Aero Shell 65	SAE 30	0 degrees – 70 degrees F
Phillips 20W-50	Type M	All Season
Phillips 20W-50	XC	Nickel Cylinders

Use mineral based AD oils only after break-in – NO synthetics

X: 815.544.8900

defects in material and
completion date of the
shall occur first.

defects in material and

any part, component or
er than PGA unless prior
rnish any parts and/or
or examination.

component or accessory

adjusted, stored,
ectives, or subjected to

vendor other than PGA

wise (except to title)
s sold by PGA.

warranties of
ges or contingent
er warranty or to

#1000056

Pho

Pop

work
over

Any
work

The
engir
notif
comj

Warr
will r


This
hand
misu


PGA
wher

No e:
other

This
merc
liabili
assur

Date





The Standard

ENGINE LOG

ASA-SE-2

*The Standard Engine Log
SE-2*

© 1991–2018 Aviation Supplies & Academics, Inc.

ASA-SE-2

ISBN 978-1-56027-326-4

All rights reserved.
Reproduction or use, without express permission,
in any manner, is prohibited.

Published by
Aviation Supplies & Academics, Inc.
7005 132nd Place SE
Newcastle, WA 98059-3153
Website: asa2fly.com
Email: asa@asa2fly.com

Printed in China

18

TRANSPORTATION USD \$12.95

ISBN 978-1-56027-326-4



Engine Record General

Manufacturer LYCO

Serial L-19038-

This engine is currently

Minimum Octane Fuel

Magneto Time

Spark Plug Gap

Manufacturer's Recom

Engine Record General Information

Manufacturer LYCOMING

Model O-360A1FGD

Serial L-19038-36A

Type Certificate _____

This engine is currently installed in aircraft: N34981

Minimum Octane Fuel _____

Oil Grade Summer _____

Winter _____

Magneto Time _____

Point Setting _____

Firing Order _____

Spark Plug Gap _____

Manufacturer's Recommended Overhaul at _____ hours

Registered Owner Record

Name JOHN RIEDEL Address 3229 W. 67TH ST.
City DAVENPORT State IA From JUNE 2019 To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Ph
Po
wor
ove

Any
wor

The
eng
noti
corr

War
will

This
han
mist

PGA
whe

No
othe

This
mer
liabi
assl

Dat

9 W, 6774 ST.

2019 To

To

To

To

To

To

To

To

To

Notes

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
--------------------	---------------------------	-------------------	-----------------------------	---

YEAR 20 DATE	RECORDING TACH TIME	T F
--------------------	---------------------------	--------

MAKE	LYCOMING	MODEL	O-360-A1F6D	S/N	L-19038-36A
Total Time	2,698.70	Hours	60294-7	Time Since Major Overhaul	ZERO

Hours

This engine was disassembled, cleaned, inspected and reassembled with necessary new parts in accordance with a major overhaul as per the manufacturer's current overhaul manual. The following accessories were overhauled or exchanged. See maintenance releases in this logbook.

Crankcase reconditioned by Divco , W.O. 126337. Installed camshaft P/N LW-18840 and tappets P/N 15B26262 new from Lycoming. Installed Overhauled Lycoming Cylinders by Poplar Grove Airmotive. Installed magneto P/N 10-682555-11, S/N B239510GR, overhauled by Poplar Grove Airmotive. Installed fuel pump P/N AF15472. Supplied carburetor P/N 10-5034, S/N BU-14-1085, overhauled by D&G Supply. Supplied starter P/N 149NL, S/N H-T012338 new from Hartzell Engine Technologies. See A.D. Compliance Record and Parts List for more details.-----END-----

All applicable airworthiness directives and related factory publications have been checked for compliance at this date. See list in this log book. This engine was test run in an FAA approved test cell and meets specifications. The aircraft engine identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service for the work performed. Pertinent details of repair are on file at this repair station under:

Work Order # 100056 **Date** 5 Jun 2019

Poplar Grove Airmotive, Inc.
 Poplar Grove Airport, Poplar Grove, IL
 FAA Approved Repair Station #YYBR664L

Joe Naebe *Joe Naebe*
 Signed for Poplar Grove Airmotive, Inc.

MANUFACTURER: Ly	
AD #	
59-10-07	cylinder b
64-16-05	fuel pump
66-20-04	oil filter a
73-23-01 R4	piston pi
75-08-09 R3	oil pump
87-10-06 R1	rocker a
90-04-06	externa
92-12-05	piston p
95-07-01	connec
95-26-02	improp
96-09-10 C	oil pun
97-15-11	piston
98-02-08	crank
98-17-11 C	crank
02-12-07	oil filt
04-10-14 C	crank

Poplar Grove A
FAA Approved Re

Ph
 Po,
 wor
 ove
 Any
 wor
 The
 eng
 not
 con
 Wal
 will
 This
 han
 mis
 PG/
 whe
 No
 oth
 This
 mer
 liab
 assi
 Dat

and Alterations
 Certificate Number of
 for specific entries.)

-36A
 Hours
 overhaul
 A detailed
 logbook.
 P/N 15B26262
 lled magneto
 N AF15472.
 P/N 149NL,
 list for more

n this log
 repaired
 for the

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
--------------------	---------------------------	-------------------	-----------------------------	---

MANUFACTURER: Lycoming **ENGINE MODEL:** O-360-A1F6D **S/N:** L-19038-36A **W.O.#** 100056

AD #	DESCRIPTION	COMPLIANCE STATUS
59-10-07	cylinder baffle clamps	N/A has new style clamps
64-16-05	fuel pump	N/A to overhauled fuel pump installed
66-20-04	oil filter adapter gasket	N/A by gasket P/N
73-23-01 R4	piston pin P/N 69650	N/A to new pins installed
75-08-09 R3	oil pump drive shaft	N/A has drive shaft with flats
87-10-06 R1	rocker arm	N/A by rocker arm P/N
90-04-06	external oil line	C/W by inspection IAW -para. (q)(1)
92-12-05	piston pin P/N LW-14077	N/A by pin P/N
95-07-01	connecting rod bolt P/N 75060	N/A by bolt P/N
95-26-02	improper fuel	N/A by aircraft registration number
96-09-10 C	oil pump	P/C/W IAW Lyc. SB524
97-15-11	piston pin	N/A by pin P/N
98-02-08	crankshaft	N/A to engine using controllable pitch prop
98-17-11 C	crankshaft	C/W by inspection IAW para (b)(1)
02-12-07	oil filter converter plate gasket	C/W IAW Lyc. SB543C
04-10-14 C	crankshaft gear	C/W IAW Lycoming SB 475C, due any prop strike

Poplar Grove Airmotive, Inc.
 FAA Approved Repair Station # YYBR664L Joe Naebe *Joe Naebe* **DATE:** 5 Jun 2019

YEAR
20
DATE

Alterations
(Date Number of
specific entries.)



Date: 8/16/2019
Tach time: 1109

Installed this engine on aircraft C
and prop governor. Installed over
with new and repaired and painted
Replaced and repaired SCAT tu
Made idle speed and mixture ad
for AD compliance records.

Carver Aero, Inc Work Order #
I certify that this engine has be
Matt Vanlandschoot



Date: 8/16/20
Tach time: 1109

Installed JPI STC SA2586
Completed FAA form 337
Carver Aero, Inc Work O
I certify that this engine h
Matt Vanlandschoot

MANUFACTURER: Lycoming **ENGINE MODEL:** O-360-A1F6D **S/N:** L-19038-36A **W.O.#** 100056

AD #	DESCRIPTION	COMPLIANCE STATUS
05-19-11	crankshaft failure	N/A by crankshaft S/N
06-06-16	crankshaft failure	N/A by crankshaft S/N
06-10-21 C	ECl connecting rods	N/A by Lycoming rods
06-12-07	ECl cylinders	N/A to Lycoming cylinders
07-04-19 R1	Superior cylinders	N/A to Lycoming cylinders
09-26-12	ECl cylinders	N/A to Lycoming cylinders
12-03-07	HA-6 carburetor	N/A by model P/N carburetor
12-19-01	crankshaft failure	N/A by crankshaft S/N
15-02-07	Prop Gov Shaft Set Screw	N/A by engine model
17-16-11	Lycoming rod bushings	N/A to new AEL13923 bushings installed

Poplar Grove Airmotive, Inc.
FAA Approved Repair Station # YYBR664L Joe Naebe *Joe Naebe* **DATE:** 5 Jun 2019

Ph
Pa
wo
ove
An
wo
Th
eng
not
cor
Wa
will
Thi
har
mis
PG
wh
No
oth
Thi
me
liab
ass
Da

and Alterations
Certificate Number of
per specific entries.)

D.# 100056

2019



Date: 8/16/2019 N34981
Tach time: 1109

Lyc. O-360-A1F6D
Total Time: 2689.3

CARVER AERO, Inc.
Municipal Airport
Davenport, IA 52806
FAA Approved Repair Station No. VRXR118L

Eng. S/N: L-19038-36A
TSMOH: 0

Installed this engine on aircraft Cessna 177B S/N 17702133 I/A/W Cessna Service Manual. Reinstalled alternator, vacuum pump, and prop governor. Installed overhauled oil cooler, new J9613-49 (4ea.) engine mounts, seven new engine hoses, replaced flexible baffling with new and repaired and painted baffles as required. Installed Reiff preheat system. Rigged prop governor, throttle and mixture cables. Replaced and repaired SCAT tubing as required. Serviced with 8 qts. Phillips X/C Mineral Oil. Performed engine run up and leak check. Made idle speed and mixture adjustments. Performed test flight. Researched and C/W AD's thru 8/16/2019. See Front of this log & AD list for AD compliance records.

Carver Aero, Inc Work Order #: 208138

I certify that this engine has been inspected I/A/W an Annual Inspection and and was determined to be in airworthy condition.

Matt Vanlandschoot

Signed: *Matt Vanlandschoot*

FAA Approved Repair Station No. VRXR118L



Date: 8/16/2019 N34981
Tach time: 1109

Lyc. O-360-A1F6D
Total Time: 2689.3

CARVER AERO, Inc.
Municipal Airport
Davenport, IA 52806
FAA Approved Repair Station No. VRXR118L

Eng. S/N: L-19038-36A
TSMOH: 0

Installed JPI STC SA2586NM temperature monitoring system and STC SA00432SE I/A/W STC instructions and drawings. Completed FAA form 337 and completed Weight & Balance dated 8/16/19. Operation Cks good.

Carver Aero, Inc Work Order #: 208139

I certify that this engine has been inspected I/A/W an Annual Inspection and and was determined to be in airworthy condition.

Matt Vanlandschoot

Signed: *Matt Vanlandschoot*

FAA Approved Repair Station No. VRXR118L

YEAR
20
DATE

YEAR
20
DATE

RECORDING
TACH
TIME

TODAY'S
FLIGHT

TOTAL
TIME IN
SERVICE

Description of Inspections, Tests, Repairs and Alterations

Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

YEAR
20
DATE

RECORDING
TACH
TIME

P
P
W
O

A
w
T
e
r
n
c
c

W
w
T
h
e
m

P
w

N
o
t

T
r
m
l
i
a
s

D



Maintenance Release Tags

Work Order 100056





N34981

**US PROPELLER
SERVICE of FLORIDA, INC.**



PROPELLER LOGBOOK