Cessna®



Airborne

Air Filter Change Reminder

Changed at: 2255.0 Hrs.
10-27-88 Date

Next Change: 2755.0 Hrs.

Parker Aerospace

AIRCRAFT LOG
AND MAINTENANCE RECORD

N 1946Q SERIAL NO. 177RG0345

Book # 2

IMPORTANT NOTICE

Dear Owner:

Federal Aviation Regulation Part 91.170 requires that the static pressure system(s) and sensitive altimeter instrument(s) be inspected every two (2) years in accordance with Part 43, Appendix E, if the aircraft is to be operated in controlled airspace under IFR.

The entry in your aircraft log lists the date on which this test was performed on your static system(s) and altimeter(s). Because these tests are accomplished during instrument and aircraft assembly, this date may be a maximum of twelve (12) months prior to the date on your Airworthiness Certificate.

Because of this difference, Cessna recommends that you retest and inspect the static system(s) and altimeter(s) at your first Annual Inspection.

In following this recommendation, a schedule will be established whereby subsequent test and inspection periods will coincide with an Annual Inspection to minimize aircraft down time.

Customer Services Department
Cessna Aircraft Company

Cessna®

AIRCRAFT LOG

AND MAINTENANCE RECORD

Record of Cessna (Make) 177RG (Model) 177RG0345 (Serial) N1945Q (Certificate)

With Engine Lycoming (Make) IO-360-A1B6D (Model) L-10167-51A (Serial)

From June 9 19 80 to _____ 19 ____

Detailing Time From 1605.6 (Hours) To _____ (Hours)

Owner _____

Address _____

FORM P121-13

EXCERPT FROM THE FEDERAL AVIATION REGULATIONS

NOTE

Since the following excerpt is subject to change, a periodic check of the latest FAR, Part 91 should be made to insure that adequate maintenance records are being kept.

"FAR 91.173 Aircraft and Engine Maintenance Records. The registered owner or operator shall maintain a maintenance record in a form and manner prescribed by the administrator which shall include a current and accurate record of the total time in service on the aircraft and on each engine, a record of inspections, and a record of maintenance required by Part 18 of this sub chapter. Such records shall be:

"(a) Presented for required entries each time inspection or maintenance is accomplished on the aircraft or engine,
"(b) Transferred to the new registered owner or operator upon disposition of the aircraft or engine involved, and
"(c) Make available for inspection by authorized representatives of the administrator or board."

INSTRUCTIONS FOR THE USE OF THIS LOG BOOK

All required data must be entered in the proper columns regularly. The column headed REMARKS is particularly important, for in that column must be entered the following information:

1. A record of all Line and Periodic inspections and results.
2. A record of all accidents in which the aircraft is involved, whether major or minor. All entries covering alterations or repairs to aircraft or propeller shall be endorsed by the certificated mechanic responsible for same, including his rating and certificate number.
3. A record of rigging changes; all repairs and alterations to aircraft or propeller; changes in engines or propellers; and a record of operation of both — installed, and also prior to installation.
4. When repairs or alterations to aircraft or propeller necessitate submission of FAA Form ACA 337 (Repairs and Alterations) the original of this form shall be incorporated in the back of this book, and become a part thereof; and each such incorporated form shall be noted in the REMARKS column.
5. A record of all repairs to instruments used on certificated airline aircraft.
6. Chronological listing of compliance with service bulletins, airworthiness directives, etc., including a description of the method of compliance.

MAKE ALL ENTRIES WITH PEN AND INK—MAKE NO ERASURES.

AIRCRAFT LOG

DATE 19	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS	ACCUMULATED TOTAL FLYING TIME IOTHS	SIGNATURE OF PILOT
9 June 1980	Tach 1605.6	serviced Battery, Brakes. Lubed Airframe. Jacked A/C. Did Retraction test on landing gear. Installed New battery. Kit in ELT Replacement Due March 83. Installed New Rod end on gear actuator Per Cessna Service Bulletin SE 79-37. Complied with Cessna service letter SE 80-6. Installed New spring on Right tie down Ring. Installed New Bulb in Left Nav Light. Installed new tip on Pitot tube. Removed Rust From Right Filler neck and Replaced "O" Ring on Cap. Removed Left Filler adapter and Replaced Fuel cap adapter with new part. Installed New Fuel cap Left side. Removed Bird Nest From tail Cone. Installed New Tip on Left stabilator. Installed New Aux Fuel pump and pump Drain tube. Replaced Vacuum Central Air filter. Replaced Vaccum Relief value Filter. Repaired Right stabalitor tip. Tightened Jamnut on Nose gear actuator Rod End. Repositioned Radio Cooling Tube Away From Control Column. Repositioned Flap cables Away From Head Liner Bracket. Service Letters Checked and complied			

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

AL
OMENCLATUR
ALTIMETER P
Date
EST IND
T (FT) ING
-1000
0 0
500
1000
1500
2000
3000
4000
5000
IC
HA
WI
DE
DI
TOTAL TIME
BY:
AIRCRAFT SERV

GNATURE OF PILOT

s. Lubed
gear.
March 83.
Service
Her SE 80-6.
lled New
. Removed
p.
apter
noved
stabilator.
. Replaced
we Filter.
e gear
way
ons
Complied

in accordance with FAR 91. 25

Date	Bearing error VOR 1	Bearing error VOR 2	Place	Signature

DATE 19____

REMARKS

Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.

with to this Date. Complied with AD-[illegible]79-08-03. installed
Fuse in Cigar Lighter wire. Complied with AD 79-18-06 Mag sent
To Bendix For Rework. AD Notes Checked and complied with
Through 80-11.

I CERTIFY THAT THIS Aircraft HAS BEEN INSPECTED IN ACCORDANCE WITH AN Annual INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. TACH TIME: 1605.6 DATE: 6-9-80
TOTAL TIME 1605.6 W.O.# 6484
BY: Ernest A Cassell Jr IA 2233113
AIRCRAFT SERVICES, INC. SALINA, KS.

I CERTIFY THAT THE ALTIMETER AND STATIC SYSTEM TESTS REQUIRED BY F.A.R. PART 91.170 HAVE BEEN PERFORMED.
THE ALTIMETER WAS TESTED TO 20,000 FT.
ON 6-9-80 BY: Ernest A Cassell Jr.
W.O.# AW02413 DATE: 6-980
AIRCRAFT SERVICES, INC. SALINA, KS.
CRS 322-29

AIRCRAFT LOG

DATE 19	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS	ACCUMULATED TOTAL FLYING TIME 10THS	SIGNATURE OF PILOT
7-14-80	Tach 1622.0	C/W AD 26-02-12 & FOUND SWITCH TO BE FAULTY. INSTALLED BENDIX					
KIT # 10-35210 IN MAG		SWITCH CHECKED SWITCH AGAIN OPERATIONAL CK OK					S Stevens Jr Thompson A-PS 1456 1933
8-1-80	Tach 1623.3	Overhaul skimmy damper adjust flap selector switch &	service with fluid & reinstall, tightens screws, oper. ck. ok.				Gregory Lee Bohn AOPS 11605166
1-16-81	Tach 1654.0	Reinstall enclosed. oper ck. ok.	EGT Gauge S/N 59081				after repair, maint release Gregory Lee Bohn AOPS 11605166
4-20-81	Tach 1687	Replaced voltage regulator					Ronald D. Ubben AOPS 17304

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

VOR Receiver operation c
in accordance with FAR 9

Date	Bearing error VOR 1	Bearing error VOR 2	Place

Sept. 15, 198
Removed
Switch in
all Checked
Ok

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25					DATE 19 ____	REMARKS
Date	Bearing error VOR 1	Bearing error VOR 2	Place	Signature		Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
						6-25-81 Tach 1699.4 Airframe inspection opened all inspection panels & floorboards, checked all cables and pulleys. Jacked aircraft, packed wheel bearings replaced brake linings, ran gear retraction
						I certify that this ~~Aircraft~~ Aircraft has been inspected in accordance with a Annual inspection and was determined to be in airworthy condition.
						Signed Ronald D. Warner A&P1730211 A.I.
						Pertinent details of the repair are on file at this agency under
						WORK ORDER NO. 10729
						DATED Sept 15, 1981
						SIGNED Ron D Warner
						For SNYDER AIRCRAFT, INC.
						AIRFRAME DIVISION
						FAA Certificate No. [illegible]
Sept. 15, 1981						Tach Time 1706.9 Removed & Replaced Down Limit Switch in wing. Checked Rigging all Checked OK.
						The End

AIRCRAFT LOG

DATE 19	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS	ACCUMULATED TOTAL FLYING TIME 10THS	SIGNATURE OF PILOT
6-6-82	Tack & power pack. Jacked nose strut.	total time 1761.6	Replaced landing gear aircraft to verify	retraction,			reSealed

Pertinent details of the repair are on file at this agency under

WORK ORDER NO. ..... 10915 .....

DATED ..... 6-1-82 .....

SIGNED Ronald D Wasson

For SNYDER AIRCRAFT, INC.
AIRFRAME DIVISION
FAA Certificate No. D03-60

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

VOR Receiver operational check in accordance with F

Date	Bearing error VOR 1	Bearing error VOR 2	Pl

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25					DATE	REMARKS
Date	Bearing error VOR 1	Bearing error VOR 2	Place	Signature	19 ____	Enter here general data with reference to "Line" and "Periodic" inspections -- Rigging Changes -- Alterations -- Repairs -- Service Letters -- and changes in propeller or engine -- as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
					7-6-82	Tach Reads 1762 Insp As per Check List, Dise Noted on WO 01619
						Clark W Carter
					Date 7-6-82 Total Time 1762 Tach	A+P 1373344
					Time 1762 I certify that this Aircraft ~~Engine~~ has been inspected in accordance with a annual inspection and was determined to be in airworthy condition.	
					Signed Clark W Carter	
					Cert. No. I # 1373344	

AIRCRAFT LOG

DATE 19	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS	10THS	SIGNATURE OF PILOT
7-26-83	Tach Time 1781.5	Total Time 1781.5	Opened wings + empennage Checked				
	Elevator + Rudder Control, Aileron +		Flap Control Cables, Pulleys, +				
	Bellcranks. Checked wheel bearings +		Brake pads. Serviced Power Pack				
	Changed ELT Batterys. ELT due July 84		Ch. ELT for Prope. Operation				
	Jacked Aircraft and ran gear check		Serviced Landing gear				
	Merle Harding A&P 501301332		Checked ADs + SBs.				
			Merle Harding A&P 1301332				

Date 7-26-83 Total Time 1781.5 Tach Time 1781.5 I certify that this Aircraft ~~has~~ has been inspected in accordance with a ..... inspection and was determined to be in airworthy condition.

Signed Robert Cushman

Cert. No. IA 1573244

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

VOR Receiver ope
in accordance wit

Date	Bearing error	
	VOR 1	VOR 2
Feb	3 -	19
mar	F	

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25					DATE 19 ___	REMARKS
Date	Bearing error VOR 1	Bearing error VOR 2	Place	Signature		Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
Feb. 3-19			84 tach time		1811	Replaced left elevator tip with
new	P/N		1732024-1-791			tip Steven D Sarlett A+P 482684520

AIRCRAFT LOG

DATE 19	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS	IOTHS	SIGNATURE OF PILOT
Sept. 20, 1984	tach 1820.3	total time			1820.3		
Inspected this Aircraft according to Cessna's Service Manual							
Removed all inspection Covers - Removed Interrior - Cleaned Aircraft							
Repacked all wheel bearings - Replaced All tires with new							
Goodyear Flight Customs - Rivited a patch inside tail Cone on							
both sides - Replaced ELT But this Bat good till Sept 1986 Operational							
Check OK - Replaced Aircraft Bat with new Concord - Retracted landing							
Gear and checked operation including emegerency System Replaced Throttle							
Gear up warning switch - drained all fuel Sumps + checked all fuel							
Screens - Checked Vacume System and Replaced Vacume Reg Filter and							
Central Air filter - Checked electrical System + lights replaced 3							
Post lights - Replaced Aero duct for Cabin Heat - Replaced all bolts							
in Nose wheel - CW AD 82-27-02 Propeller Blade shank failure							
by dye Check of Propeller blades painted Prop and reinstalled on							
Aircraft - Checked and lubed all controls I Certify that this Aircraft							
has been inspected in Accordance with a Annual Inspection and was							
determined to be in Airworthy Condition A&P 1845 46784 I/A							
Boyd Roland							

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

VOR Receiver operation chec
in accordance with FAR 91.2

Date	Bearing error VOR 1	Bearing error VOR 2	Place
11-7-84			
Remove			
Acleaned			
Rear			
Rear			
A&P4			

GNATURE OF PILOT

e Manual
ned Aircraft
new
ere on
1986 Operations
d landing
placed Throttle
all fuel
filter and
ced 3
all bolts
failure
lled on
is Aircraft
and was
off
l

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25					DATE	REMARKS
Date	Bearing error VOR 1	Bearing error VOR 2	Place	Signature	19 ____	Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.

AIRCRAFT LOG

DATE 19	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS	ACCUMULATED TOTAL FLYING TIME 10THS	SIGNATURE OF PILOT
Sept 6 1985	tach	1873					
Completed 50 hr inspection according to Cessna Service manual & Certify that the aircraft has been inspected in accordance with a 50 hr inspection and was determined to be in Airworthy Condition A+P 1845467 84 IA		Boyd Roland					

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

VOR Receiver in accordance	
Date	Bearing err
	VOR 1 / VOR
Mar 6	
inspe	
manu	
instal	
bearings	
ELT ope	
air fiel	
system	
battery	
spinn	
fuel s	
in de	
determ	

AIRCRAFT LOG

SIGNATURE OF PILOT

Cessna
ft best
60 hrs
Airworthy

VOR Receiver operation checked in accordance with FAR 91.25					DATE	REMARKS
Date	Bearing error VOR 1	Bearing error VOR 2	Place	Signature	19 ____	Enter here general data with reference to "Line" and "Periodic" inspections – Rigging Changes – Alterations – Repairs – Service Letters – and changes in propeller or engine – as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
						Nov 07 1985 tach 1886.5 total time 1886.5 inspected this aircraft according to Cessna Service manual - installed Cessna Kit SK177-31 nose gear down switch - prepacked gear retraction - repacked all wheel bearings + lubed gear - inspected all controls and lubed ELT operation OK + Batt good till Sept 1986 - AD 84-26-02 induction air filter checked and hours remaining 2191 - checked electrical systems - checked Aircraft Battery for condition removed + cleaned Battery Box - checked vacuum system - checked propeller hubbolts spinner and prop for oil leaks - Drained all fuel sumps + checked fuel screens - I Certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in Airworthy Condition A&P 484546784 EA Boyd Raburn

AIRCRAFT LOG

DATE 19	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS	ACCUMULATED TOTAL FLYING TIME 10THS	SIGNATURE OF PILOT
10-17-86	TACH	1903					
	ELT REMOVED. BATTERY ORDERED. REPLACED ALL BRAKE LININGS. SERVICED SHIMMY DAMPNER. CHECKED GEAR RESERVOIR, RETRACTION TEST. REPAIRED LEFT DOOR LATCH. LEFT WING STROBE POWER SUPPLY INOP. NEW ELT BATTERY 10-88						

I certify this AIRCRAFT has been inspected in accordance with a ANNUAL inspection and found airworthy.

R. J. Blackhurst --R. J. Blackhurst, A&P 1570611

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

VOR Receiver in accordance	
Date	Bearing err
	VOR 1 VOR
10-20	

AIRCRAFT LOG

SIGNATURE OF PILOT
INOP

VOR Receiver operation checked in accordance with FAR 91.25					DATE	REMARKS
Date	Bearing error VOR 1	Bearing error VOR 2	Place	Signature	19___	Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
10-20-86						
						The ATC Transponder tests and inspections required by FAR 91.172 were performed on this date and found to comply with FAR 43 Appendix F. Details of this inspection are on file at this Repair Station under W.O. # 3002 ATC Transponder UT-78 Ser. No. 70004 Date 10-20-86 Signature Donald E. Anderson South State Avionics, Inc. FAA Repair Station CH4-72 Mankato, MN 56001
						I certify that the static systems tests required by FAR 91.171 have been performed and the altimeter has been certified I/a/w Part 43 Appendix E, by Repair Station CH4-72 on 10-20-86 Donald E. Anderson 10-20-86 Signature Date South State Avionics, Inc. Mankato, MN 56001

AIRCRAFT LOG

DATE 19	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS	ACCUMULATED TOTAL FLYING TIME 10THS	SIGNATURE OF PILOT
1-7-87	INSTALLED	AERO-SONIC ENCODING	ALTIMETER IN PLACE				
	OF ORIGINAL ALTIMETER: ENCODER		FUNCTIONALLY CHECKED				
	& STATIC SYSTEM CHECKED FOR LEAKS: INSTALLED AR/NAV						
	15B LORAN SYSTEM IN ACCORDANCE WITH EQUIP MANUFACTURERS						
	INSTALLATION MANUAL & ALL PERTINENT FAR'S; SEE						
	337 FORM DATED 1-7-87: ALL NECESS ARY NOTATIONS						
	MADE IN EQUIP LIST & W+ BAL SHEET.						

AIRCRAFT ELECTRONICS
Sanborn Hangar
St. Paul Downtown Airport
St. Paul, MN 55107
(612) 228-0823

Raymond F. Mabrey

Raymond F. Mabrey
#1883096 C.R.S. 3476

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

VOR Rece in accorda		
Date	Bearing	
	VOR 1	V
6-19-		
6-24-8		
7/6/87		
7/16/87		
7-26-8		
7-26-8		

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25					DATE	REMARKS
Date	Bearing error VOR 1	Bearing error VOR 2	Place	Signature	19 ____	Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
6-19-87			TT		1998	
			Removed Alternator and Regulator and had checked, Reinstalled.			
			Replaced all battel seal with new. Installed new gear horn			
			micro switch. Replaced bad Cowl Fasteners. Installed new			
			Fire extenguisher.			
						Eblon Enstal 4764B3590 A+P
6-24-87			Replaced Old Concord with new Rebat 12 volt Battery			
7/6/87			OVERHAWED			O.G.
7/16/87			OVER HAULED			TURN COORINATOR
7-26-87			Installed			Bracket pre filter T.T. 2010
7-26-87			C/W AD		86-24-07	Engine Controls nuts T.T. 2010
			C/W AD		81-15-03	Bracket filter Eblon Enstal 4764B3590 A+P

AIRCRAFT LOG

DATE	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS	10THS	SIGNATURE OF PILOT
10-19-87	Tach 2053	T.T. 2052					
	I Certify that this aircraft has been inspected in accordance with the ANNUAL inspection and a list of discrepancies has been provided to the owner. The discrepancy is non compliance with A.D. 86-19-11. Compliance with that A.D. will make this Aircraft A/C weight at this time A.D. 87-20-03 C/W by ing. of seat rails. Packed left wheel bearings.						
							C.A. Mann
							FA 2172659
10/26/87	Tach & Total Time 2054.2						
	Installed fuel tank quick drain & preflight fuel system checklist to comply with A.D. 86-19-11						
							Mike A Miller
							A&P 501-27467

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

VOR Re... in accor...	
Date	Beari... VOR
11/14/87	
3/12/88	
7-20-8	

URE OF
OT

ma.ings.

89

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25					DATE	REMARKS
Date	Bearing error VOR 1	Bearing error VOR 2	Place	Signature	19 ____	Enter here general data with reference to "Line" and "Periodic" inspections – Rigging Changes – Alterations – Repairs – Service Letters – and changes in propeller or engine – as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
11/14/87			TT 2059.6			
			Installed NEW alternator belt. Recaffyed Alternator, Rein-			
			stalled prop and Re saffyed.			
						Ellen Ewing 476483580 A&P
3/12/88			TT 2105			
			Installed new P.6.			
7-20-88			TACH TIME		2201	
			Rotate Left		MAIN TIRE - Replaced Brake Pad Both	
			MAIN Wheels.			Stanley P. Kinston 473526000 A&P

AIRCRAFT LOG

DATE 19	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS	ACCUMULATED TOTAL FLYING TIME 10THS	SIGNATURE OF PILOT
10-27-88	Tach 2255.0 Total Time 2255.0		Annual Inspection As Per				
		Cessna Inspection Guide.	Replaced Rear Seat Reclining				
		Panels, Replaced Instrament	Air Filter and Vachum Relief				
		Filter. Cleaned and	Repacked All Wheel Bearings. Performed				
		Gear Retraction Test.	Replaced ELT				Batt. Pack Next
		Due 11-90.	Complied With AD 76-07-12 Bendix Switches				
		Checked OK; Complied With	AD 78-09-07 R3 as per Bendix				
		SR 599B Next Due At 2755. Tach. Time;	Complied With				
		AD 87-20-03R1 Seat Rail Insp	Must Be Inspected again				
		at 2355. Tach. Time. Complied With	AD 88-17-12 By				
		Installation of STC SA 2344C	= see 337 This Date. For				
		Complete AD List See Back of	This Log.				I certify
		That This Aircraft Has been	Inspected In Accordance				
		With An Annual Inspection	and was Determined				
		To Be In Airworthy Condition.					
			Morgan R. Stroh				
			AP 507746 IA				

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

VOR Rece in accorda		
Date	Bearing	
	VOR 1	
Perform		
FAR 91		
proced		
and F		
Sess		
Mai		
AIRCRA		
Sanbor		
St Paul		
St Paul		
Cla		
Charle		

TURE OF
LOT

s Per
eat Reclining
m Relief
gs, Performed
Next
lix Switches
er Bendix
With
again
By
e. For
ify
ordance
ained

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25				DATE
Date	Bearing error VOR 1	Bearing error VOR 2	Place	Signature	19 ____

REMARKS

Enter here general data with reference to "Line" and "Periodic" inspections – Rigging Changes – Alterations – Repairs – Service Letters – and changes in propeller or engine – as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.

Performed inspection required by FAR 91.172 in accordance with procedures outlined in appendix E and F of FAR 43. C.R.S. 3476

Sperry / CC-3171 7C004
Make Model Serial No.

AIRCRAFT ELECTRONICS
Sanborn Hangar
St. Paul Downtown Airport
St. Paul, MN 55107 (612) 228-0823

Charles Rothmeier 11-6-89
Charles Rothmeier #2364642 Date

I certify that the altimeter and static pilot system test required by FAR 91.171 have been performed. The altimeter has been tested to 15,000 ft. and the automatic pressure altitude reporting to 15,000 ft.

AIRCRAFT ELECTRONICS
Sanborn Hangar
St. Paul Downtown Airport
St. Paul, MN 55107 (612) 228-0823
C.R.S. 3476

Charles Rothmeier, 11-6-89
Charles Rothmeier #2364642 Date

AIRCRAFT LOG

DATE 19	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS	10THS	SIGNATURE OF PILOT
11-6-89	Tach time 2399.9	total time 2399.9.	Inspected this Aircraft according				
	to Cessna's Service manual with reference to F.A.R. 43 appendix D. Removed						
	all inspection panels. removed interior and floor panels. Cleaned						
	exterior and interior of aircraft. Repacked all wheel bearings Checked						
	electrical system and lights. Replaced tail static wicks Removed						
	propeller for overhaul reinstalled propeller. Maintenance release tag						
	in back of log book. Replaced left aileron attach bolt. List of						
	minor discrepancies given to aircraft owner. I certify that this						
	aircraft has been inspected In accordance with an annual inspect						
	ion and was determined to be in Airworthy Condition						
	Carl Thomas A&P 472742467						
11-6-89	TACH 2399.9 TTAF 2399.9						
	C/W AD# 87-20-03 R1 AMNDT 39-5863 DATED			4/4/88		by	INSPECTION. AD NEXT
	DUE AT 2499 TACH -						
	C/W AD# 76-07-12 AMNDT 39-3024 DATED			8/30/77		by	OPERATIONAL check.
							NEXT DUE AT 2499 TACH

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

VOR Receiver in accordance		
Date	Bearing err	
11/89	VOR 1	VOR
		A
		E
		I
12-20-8		
3-		

TURE OF
LOT

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25					DATE	REMARKS
Date	Bearing error		Place	Signature	19 ___	Enter here general data with reference to "Line" and "Periodic" inspections – Rigging Changes – Alterations – Repairs – Service Letters – and changes in propeller or engine – as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
11/89	VOR 1	VOR 2				
		AD	#78-09-07 R3 AM			NOT 39-4538 DATED 1/17/83 Due at 2755 TACH
			ELT Battery			Due 11/90
			I			CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN
						ACCORDANCE WITH AN ANNUAL INSPECTION AND FOUND TO
						BE IN AIRWORTHY CONDITION – S Borm A&P 476485442 FA –
12-20-89			TACH 2405			INSTALLED R&L MAIN TIRE & TUBES END
						Lonnie A&P 472509324
						3-27-90 Tach 2705
						Replaced 2 lower cowl mounts, replaced 2 mushroom
						cowl & gear leg fwd brg. Adjust T.C.C.S. Lev. replaced
						rt. tail light, Weld bolt brackets
						John C. Potter A&P# 1974777.

. AD next

check.
9 TACH

AIRCRAFT LOG

DATE 1990	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS	10THS	SIGNATURE OF PILOT
8-15-90	Tech 2424-9	Replaced the Following Parts after nose gear collapse replaced Both nose gear doors (aft), Both Carl Flaps & Carl mounts, upper & lower gear struts replaced drag link Bolt, replaced Both nose gear deburator rods, replaced Squat Switch. gear assembled & and rigged as per Cessna 177RG Service Manual & run thru 25 Full Swe Cycles, Aircraft test Flown and found to be OK				

MAINTENANCE RELEASE

The component identified was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repairs are on file at this Repair Station under work order 2769, Date 8-17-90,
Signature [signature], Type of Certificate/Number APX164492A for CRS BDKR393C, STC Aviation, Inc., St. Cloud, MN 56302.

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

VOR Receiver o in accordance w		
Date	Bearing erro	
	VOR 1	VOR 2
12-4- Remov inspect Replac left rating light rear regla arrang return cable at fre -do- surfa		

MAINTENANCE RELEASE

The aircraft instrument identified on the reverse side of this tag was repaired and inspected in accordance with current Civil Air Regulations and was found airworthy for return to service. Details of repair on Work Order

Number 40308 Dated Nov 30, 1990

are on file at this agency.

Authorized Signature [signature]

WILLIAMS INSTRUMENT SERVICE, F.A.A. App. Rep. Sta. UN2R220L
Class 1, 2, 3 and 4

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25				DATE
Date	Bearing error VOR 1	Bearing error VOR 2	Place	Signature
				19__

REMARKS

Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.

12-4-90 Tach 2469 H-2469, H-2469 Removed artificial horizon, overhauled by Williams instrument & reinstalled / replaced both plexiglass covers "O" rings / replaced cowl flap front hinge halfs & soft flex hose / left hand pins replaced & cowl latch adjusted, both pins lubricated / replaced all static hose - nylon reinforced / replaced one tail light assy tail cone, adjusted both position lights / replaced baggage compartment door seal, adjusted left fuel drain / replaced seal on right sparger, adjusted left fuel drain / replaced cable for right & left aileron cables at both cranks / 2 turn tach, CW AD 87-20-03 R1 seat rails - dbl plunger, annual CW AD 76-07-12 Bendix magneto switch - ck - ok due @ 2569 H,

I certify that this aircraft/~~engine~~ has been inspected in accordance with a ~~100 hour~~/annual inspection and was found to be in an ~~airworthy condition~~.

John A. Yoke #1874737 IA

AIRCRAFT LOG

DATE 19	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS	ACCUMULATED TOTAL FLYING TIME 10THS	SIGNATURE OF PILOT
1/30/91	tach	2486.0					
	Installed	I-COM	MODEL PM1000	SCE	337 Hrs		to date

FORMS

MAINTENANCE RELEASE

The equipment or component identified above was repaired and inspected in accordance with current Federal Regulations and was found airworthy for return to service.
Pertinent details of the repair are on file at this agency on work order No. 2536

Nav-Com Contractor, Inc.
FAA Repair Sta. KL5R992M
Garrision, MN 56450

Date 1/30/91
Signed Patrick A Wiese

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25					DATE	REMARKS
Date	Bearing error VOR 1	Bearing error VOR 2	Place	Signature	19 ___	Enter here general data with reference to "Line" and "Periodic" inspections – Rigging Changes – Alterations – Repairs – Service Letters – and changes in propeller or engine – as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
7/18/91			TACH 26		10.1	REMOVED FRONT TIRE & TUBE. REPACKED FRONT BEARINGS. CHECKED ALL COMPONENTS. REPLACE FRONT TIRE W/ NEW GOODYEAR 5.00-5 4 PLY FLIGHT CUSTOM II TIRE P/N #301-015-090 & NEW GOODYEAR 5.00-5 TUBE. INSPECTED & CHECKED SERVICEABLE
						REMOVED LH LANDING LIGHT & REPLACED W/GE #4313-250W LIGHT. OPS ✓ OK.
25 OCT 91			TACH TIME 2656.1			AIRFRAME TT 2656.1 COMPLETED 100 HR INSPECTION LIST. REPAIR BAGGAGE DOOR ROD ATTACH POINT REPLACE LEFT PILOTS RUDDER PEDAL. REROUTED MISC WIRES BEHIND PANEL FOR CLEARENCE. LUBE & FREED UP ELEVATOR TRIM PULLEY IN FLOOR. REPLACED NOSE GEAR ABRASION PAD. REPLACE MAIN GEAR UP STOP BUMPERS. REPLACE BRAKE PADS. REBUILD BOTH ~~GEAR~~ BRAKE CYL'S. PACK BEARINGS. BLEED BRAKES. REPAIRED NOSE GEAR DOOR HINGE. REPAIRED INST. LIGHT RHEOSTATS.

CONT ON NEXT PAGE

AIRCRAFT LOG

DATE 19	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS	ACCUMULATED TOTAL FLYING TIME 10THS	SIGNATURE OF PILOT
25OCT91	TACH	2656.1	CONTINUED FROM PREVIOUS PAGE —				
REPAIRED COMPASS LIGHT WIRES. REPLACED LEFT DOOR							
& CATCH BRACKET. REPLACED RT AILERON PUSH PULL TUBE BALL							
ENDS. TIGHTENED ELEVATOR TRIM TAB ROD BOLT. REMOVED							
BIRDS NEST IN TAIL. TIGHTENED ELEVATOR CABLES. ADS CHECKED							
THRU ISSUE 91-19. COMPLIED WITH AD 87-20-03 R2, B4							
INSPECTING SEAT TRACKS & PINS. C/W AD 76-07-12 BENDIX							
MAG SWITCH BY GROUND RUNNING & TESTING.							
DATE 25OCT91 TIME 2656.1							
I CERTIFY THAT THIS (AIRCRAFT) OR ENGINE)							
HAS BEEN INSPECTED IN ACCORDANCE WITH							
AN (ANNUAL) OR 100 HR) INSPECTION AND							
WAS DETERMINED TO BE IN AN AIRWORTHY							
CONDITION							
SIGNED Bob Saulsbury							
A & P A&P2225738 IA							

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

VOR in ac	
Date	Be / VO
1 MAR	92
1 MAR	

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25					DATE
Date	Bearing error VOR 1	Bearing error VOR 2	Place	Signature	19 92
1 MAR 92					1 MAR
1 MAR 92					

REMARKS

Enter here general data with reference to "Line" and "Periodic" inspections – Rigging Changes – Alterations – Repairs – Service Letters – and changes in propeller or engine – as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.

I certify that the altimeter, static system, transponder and altitude reporter tests required by FAR'S 91.411, 91.413 & 91.217 have been performed and found to be within the limits of FAR appendixes E & F and AC 43.6a.

Tested to: ~~20000~~ ft.

Altimeter Model Aerosonic #1sn 266930 #2sn None

Transponder Model KT-78 #1sn 7C004 #2sn None

Altitude Reporter Aerosonic #1sn 266930 #2sn None

Signed:

Name Scott Borgerding # 00245605 94

AIRCRAFT ELECTRONICS, BLAINE, MN. 55434

CRS# QM2R114L Work Order # 6303B 2/11/92

1 MAR COMPLIED WITH SERVICE BULLETIN SEB86-5R1: INSTALLED CESSNA P/N{0705097-1 IN ACCORDANCE WITH INSTRUCTIONS 0705098-1

REMOVED LORAN R-15 FOR O/H. A/C PLACARDED.

AIRCRAFT LOG

DATE 19 92	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS	ACCUMULATED TOTAL FLYING TIME 10THS	SIGNATURE OF PILOT
19 MAR 92			RE-INSTALLED ARNAV R-15 LORAN UNIT				
			PANEL MOUNT AND OPERATIONALLY CHECKED AFTER FACTORY OVERHAUL & UPDATE. UNIT SERIAL # 51156				P/N 453-0108
REPAIR: A/P FAA # MMA		551-036	DATED 3-11-92 REPAIR ORDER #			4/10	80. BY "LR".
23 APR 92	2688.1 TACH, 2688.1 TSN		CHANGED ENGINE OIL AND FILTER WITH 7QTS SHELL 15W50 & CHAMPION OIL FILTER P/N				
28 APR 92	2688.1	SMS	① REMOVED OLD BATTERY MODEL GILL G35D REPLACED WITH GILL MODEL G35D NEW BATTERY FILLED & TESTED AS PER MANUFACTURERS SPECS — SATISFACTORY. RE.				
		578.1 TSN	② REMOVED AIR FILTER & REPLACED W/NEW BRACKET P/N BA5105 PER MANUFACTURS SPECS				
		433.1 TSN	③ REMOVED VACUUM SUPPLY FILTER & REPLACED W/NEW PART # P/N D9-14-5 PER MAN. SPECS. SATISFACTORY — END				

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

VOR Rece
in accord

Date	Bearing
19 MAR 92	VOR 1
19 MAR 92	+/

ATURE OF
ILOT

WITH
FILTER

35D
NEW BATTERY
ECS —

9 W BASTOS

PACKAGE
END
66614

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25					DATE	REMARKS
Date	Bearing error		Place	Signature	19 ___	Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
	VOR 1	VOR 2				
19 MAR 72	+1	+2	085° FR 265° TO - GROUND ANE			

Continued in Book 3

MEMORANDA

Date	
6-9-80	Complied with service letter SE-79-37 Replaced M/L/G Rod end Ernest Cissell AAP2233
6-9-80	Complied " " " SE-80-6 Installed service kit SK177-38 Ernest Cissell

MEMORANDA