


S/N: 740180

#2



EAST COAST PROPELLER SERVICE INC.

PROPELLER LOGBOOK

Hub M

Blade L

Diamet

Hub Se

Blade S

No. 1

No. 2

No. 3

No. 4

No. 5

High

Feath

Gover

PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model B2D34C208

Blade Design 82 PA-6

Diameter _____

Hub Ser. No. 740180

Blade Ser. Nos.

No. 1 B29448

No. 2 B29449

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High 26.0° Low 12.1°

Feather ✓ Reverse ✓

Governor Model _____

RIGHT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. No. _____

Blade Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____


PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
7-26-12		McCauley Propeller Model B2034C208 S/N 740180 was overhauled this date. See Yellow tag for details.	
MAINTENANCE RELEASE			
The component identified above was repaired and inspected in I.A.W. regulations of the FAA and was found airworthy for return to service for work performed. Pertinent details of the repair are on file at this agency under work order # <u>ER 9481</u>			
			
East Coast Propeller Service, Inc			For
2079 Main Street			
Litt 2, PA 17543			
FAA REPAIR STATION #E65R064Y			

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
9/29/2012	1550.9	I CERTIFY THAT THIS Propeller	
	TSOH 5.8	HAS BEEN INSPECTED IN ACCORDANCE	
		WITH A ANNUAL INSPECTIONS AND	
		AT THIS TIME HAS BEEN DETERMINED	
		TO BE IN A AIRWORTHY CONDITION	
		<i>Robert A. Bunn</i>	
		AMP 3269060 FA	

MAINTENANCE RECORD

Model: McCauley
Model: B2D34C208/82PA-6

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE

TACH

SIGNATURE

DATE: 10/01/2013

Propeller Model: McCauley B2D34C208/82PA-6

TTP: 106.4

S/N: 740180

Registration: N34904

Inspected Propeller in accordance with 14CFR:43 Appendix D annual inspections. Operational check of engine/propeller good.
NO applicable AD,s at this time.

I certify that this **Propeller** has been inspected in accordance with an annual inspection and at this time has been determined to be in a airworthy condition.

Patrick Buono
A&P 3269060 IA

Patrick Buono

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
11/15/2014	TTP 410.00	Inspected Propeller in accordance with T4 CF443 APP D Annual inspection NO AD. Applicable at this time.	
		<i>Robert Russell</i>	
		ADP3269000 FA	

Aviation Plus LLC

262-656-1260

Aviationplusllc.com

11/23/2015 N34904 Tach 2128 SPOH 583

All routine items checked per inspections sheets. I certify that this propeller has been inspected in accordance with annual inspection and was determined to be in an airworthy condition.

Robert Russell


Robert Russell 3411885IA


262-656-1260
Aviationplusllc.com

All routine items checked per inspections sheets. I certify this propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.

Robert Russell 34118851A

[illegible]





EAST COAST PROPELLER SERVICE INC.

2079 Main Street, Lititz, PA 17543
800/875-6377 • 717/627-7407 • Fax 717/627-7409

FAA Approved Repair Station: #E65RO64Y
