#1 new prop N52944

Closed
9/25/14

McCAULEY™

PROPELLER LOGBOOK

Owner Name _____

Address _____

_____

Propeller Model B2D34C207-B

Blade Model G-78TCA-0

Hub Serial No. 080568

Blade Serial No. 1 ABH26313

2 ABH26315

3 _____

4 _____

INSTALLATION HISTORY

Date	Aircraft Model & Registration Number	Engine Serial Number & Position
MAY 14 2008	THIS PROPELLER WAS MANUFACTURED NEW AT McCAULEY PROPELLER SYSTEMS, INSPECTED AND FOUND TO BE AIRWORTHY ON THIS DATE.	

MAINTENANCE & SERVICE RE

Date	Description of Work	Approved Repair Station Certificate No.

DATE: 9/5/2008
A/C TSN:
PROP TT: 0
TACH: 6115.54

PROP MODEL: B2D34C207-B
PROP S/N: 080568
REG. NO: N52944
WORK ORDER: 20023

Smyrna Air Center Inc.
Repair Station No. RG4R491M
300 Doug Warpoole Road
Smyrna, TN 37167
Phone: (615)459-3337

Prop Entries

Removed propeller P/N B2D34C207/78TCA-O, S/N 080568 due to prop strike. Installed new McCauley propeller P/N B2D34C207/78TCA-0 S/N 080568 IAW McCauley operators manual. (see McCauley Propeller Systems 8130-3 dated May 14. 2008). Ground ran propeller; operational check normal. No leaks noted.

The aircraft and/or component(s) on N52944 was repaired and/or inspected in accordance with current Federal Aviation Regulations and was found Airworthy for return to service. "Pertinent details of the repair are on file at this repair station No. RG4R491M under Work Order No. 20023 Dated 9/5/2008

DATE: 9/5/2008 SIGNED:

Michael Miles
Certified Repair Station No. RG4R491M

Work Order: 20023

Printed by EBis 3 (datcomedia.com)

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

SRT AVIATION, INC
Mount Vernon, Illinois - MVN

Propeller - **N52944** **June 11,2009**
Model – B2D34C207-B **SN - 061922**
Tach – 6206.94 **PTT – 91.4** **SMOH – NA** **ACTT – 6206.94**

Scheduled Maintenance

Inspected Propeller IAW Cessna 177RG & McCauley Maintenance Manuals and FAR Part 43 APP D checklists for 100 hours.

Airworthiness Directives/Service Bulletins

Reference Compliance data sheets dated this date 6/10/2009. AD's checked through current issue.

I Certify that this **Propeller** has been inspected in accordance with an **Annual / 100 Hour** inspection and was determined to be in an airworthy condition.

Shawn C. Sayle
AP4908251881A

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

OMB Control No. 2120-0018 01/12/2009

1. Approving National Aviation Aviation Authority/Country:	2. **AUTHORIZED RELEASE CERTIFICATE** FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG	3. Form Tracking Number:
FAA/UNITED STATES		**17321**
4. Organization Name and Address:	**AIRCRAFT PROPELLER SERVICE, INC.** **290 LARKIN DRIVE** **WHEELING, IL 60090** **EY2R811K**	5. Work Order/Contract/Invoice Number: **98302 / 53144 w/attached pages 1 thru 1 Dated: 06/21/2010**

6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
1	McCAULEY PROPELLER ASSEMBLY	B2D34C207/78TCA-0	N/A	1.00	080568	WARRANTY

13. Remarks:

WARRANTY per: SPM100 R: 4 (6/1/2007), MPC200 R: 1 (2/1/2008)

COMPLIED WITH:

AD: NONE

S/B: NONE

S/L: NONE

OTHER: N/A

	SERIAL #	TSN	TSO/TSMI
ASSEMBLY:	080568	215.5	N/A
HUB:	080568	215.5	N/A
BLADE 1:	ABH26313	215.5	N/A
BLADE 2:	ABH26315	215.5	N/A

The next action required on this component is within SEE TSN
OR LAST O/H.

Full detail of the work specified in Block 12 is on file within this agency.

...information is 2120-0018. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at ...nce Ave. SW, Washington, DC 20591, Attn: Information Collection Clearance OFficer, ABA-20

...check eligibility with applicable technical data ... aircraft may be flown. ... maintenance records must contain an installation ...

Aircraft Propeller Service, Inc.
290 Larkin Drive · Wheeling, Illinois 60090-6456
(847) 541-1133 / (800) 323-4130 · CRS EY2R811K
Fax (847) 541-0176 · EASA.145.5126

TBINSP REPORT
Quote #: 98302
Work Order #: 98302
Work Type: RESEAL
Serial #: 080568
Part Number: B2D34C207/78TCA-0
Date Printed: 6/21/2010
Page: 1

Aircraft Propeller Service, Inc.

Quote #: 98302

Customer: CESSNA AIRCRAFT COMPANY

Page

To: MCCAULEY PROPELLER-WARRANTY
P.O. BOX 949
WICHITA, KS 67201
USA

Ship To: AVIATION PLUS LLC
9870 52ND STREET
KENOSHA, WI 53144
USA

Cust PO #: PENDING

Code: 010640

Site: 1

Fax #:

Email:

Entry Date: 6/17/2010

Contact:

Phone #:

Terms: NET 30

1 MC2-RS-CS McCAULEY PROPELLER RESEAL

2 GA ADDITIONAL PARTS REQUIRED

Parts	PN/Description	Discrepancy	Condition	Qty
	A1634-9 BALL BEARING		New	64
	B4138 GASKET		New	1
	A1633-12 O-RING		New	1
	A3150-5 PIN		New	2

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
Propeller S/N 080568		**TSN** 215.5	**TSO** N/A	
This propeller has been serviced as per the 8130-3 tag dated JUNE 21/2010 under Work Order 98302 Aircraft Propeller Service, Inc. Wheeling, Illinois CRS EY2R811K			JAA.5126	

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signature Repairman and Station Certificate Number

Aviation Plus LLC
262-656-1260
aviationplusllc.com

06/23/2010 N52944 Tach 6329 TTP 214

Prop reinstalled after warranty reseal by Aircraft Propeller Service, WO#98302. All routine items checked per inspection sheets. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.

Robert Russell 3411885IA

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

Authorized Signatures

SRT AVIATION, INC
Mount Vernon, Illinois - MVN

Propeller - **N52944** **June 20, 2011**
Model – B2D34C207-B **SN - 080568**
Tach – 6431.79 **PTT – 316.25** **SMOH – NA** **ACTT – 6431.79**

Scheduled Maintenance

Inspected Propeller IAW Cessna 177RG & McCauley Maintenance Manuals and FAR Part 43 APP D checklists for 100 hours.

Airworthiness Directives/Service Bulletins

Refer to Aircraft Registration Profiled dated June 20, 2011. Researched through current issue.

I Certify that this **Propeller** has been inspected in accordance with an **Annual / 100 Hour** inspection and was determined to be in an airworthy condition.

Shawn C. Sayle
AP4908251881A

MAINTENANCE & SERVICE HISTORY

Aviation Plus LLC
262-656-1260
aviationplusllc.com

07/01/2012 N52944 Tach 6558 TTP 443

Performed prop balance to .05 IPS. Added 7 grams weight. All routine items checked per inspection sheets. I certify this propeller was inspected in accordance with an annual inspection and was determined to be in an airworthy condition.

Robert Russell 3411885 IA

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

DATE	HOBBS	DESCRIPTION OF WORK	SIGNATURE
14 Aug 13		Disassembled (1) propeller m/n B2D34C207-B s/n 080568 repaired grease leak c/w s/b 119A, s/l 87-3. Assembled, greased, painted tips and balanced. Bld. Dwg.#	

SERVICEABLE PART

MANUFACTURER Hartzell

PART NAME Propeller

MODEL B2D34C207-B

PART NO

SERIAL NO 080568

REMARKS: Disassembled repair c/w s/b 119A, s/l 87-3. Assembled, greased, painted tips and balanced. Bld. Dwg. # G-78TCM-0 #1) HBH26315. #2) HBH26316.

ACCOMPLISHED BY Timms

THE AIRCRAFT PROPELLER OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER:

Order No. 12757 Date 14 Aug. 13

Signed _____
Signature of Authorized Representative

FOR: H & H PROPELLER SERVICE
Burlington Municipal Airport
Burlington, NC 27215

F.A.A. REPAIR STATION NO. PS4R451M;

ages 11 & 12

MAINTENANCE & SERVICE HISTORY

DATE	HOBBS	DESCRIPTION OF WORK	SIGNATURE
14 Aug 13		Disassembled (1) propeller m/n B2D34C207-B s/n 080568 repaired grease leak c/w s/b 119A, s/l 87-3. Assembled, greased, painted tips and balanced. Bld. Dwg.# G-78TCA-0 #1)ABH26313 #2) ABH26315. **H & H PROPELLER SERVICE, INC.** **3439 S. AVIATION DR.** **BURLINGTON, NC 27215** **FAA REPAIR STATION PS4R451M** **1-800-334-6437**	

See FAA A.D. & Factory Service Bulletins On Pages 11 & 12

RY

ATURE

ages 11 & 12

F.A.A. AIRWORTHINESS DIRECTIVE AND SERVICE BULLETIN/ LETTER COMPLIANCE RECORD

Date	Total Propeller Time	Time Since Overhaul	A.D./Bulletin/Letter Number	Authorized Signatures Repairman and Station
8-23-13	Tach 6821.4		Reinstalled this prop on C177RG	
N52944 S/N 177RG1315			after being resealed by H & H Propeller	
Service. Satisfied with .041 safetywire. I certify that this prop has				
been inspected in accordance with a 100hr/annual inspection				
& is approved for return to service. — Samuel Barnes				
			A+P	24264424 IA

MAKE: Cessna
N52944
MODEL: 177RG
S/N: 177RG1315
TACH: 6926.70

Propeller Log

Resecured both propeller spinner fillets.

Justin K. Miller
A&P2789189

Miller Aviation, LLC
miller.aviation@hotmail.com

286 Aviation Blvd.
Lancaster, SC 29720

Date: 2/4/2014

END

Miller Aviation, LLC
Miller.Aviation@hotmail.com

286 Aviation Blvd.
Lancaster, SC 29720

MAKE: CESSNA
S/N: 177RG1315

Model: C177RG
TTAF: 7023.82

Reg. No: N366P
Tach: 7023.82

Prop Log

TNEW: 908.28

Date: 9/25/14

C/W 100HR Inspection as per FAR 43 Appendix D. Checked Ads through 9/25/14 and placed a listing in aircraft records. I certify that this propeller has been inspected in accordance with an annual 100 Hour Inspection and was determined to be in an airworthy condition.

Justin K. Miller
A&P2789189

END

9-4-15	Tach 7192.13		I certify that this prop has been inspected in accordance with a 100hr/annual inspection & is approved for return to service. Samuel Barnes A&P2426446424 IA	
	entry moved to #2 logbook for sequence			

closed 9/25/14

see #2