

# PROPELLER MAINTENANCE RECORDS

Log No. \_\_\_\_\_

Aircraft Registration No. N10420  
Propeller Manufacturer McCawley  
Hub Model B2D34C211  
Blade Design No. 82PCA-6  
Hub Serial No. 751661

Blade Serial No's.  
1. B35411  
2. K43269  
3. \_\_\_\_\_  
4. \_\_\_\_\_

Pitch Range:  
High \_\_\_\_\_ Low \_\_\_\_\_  
Feather \_\_\_\_\_ Reverse \_\_\_\_\_

Governor Manufacturer \_\_\_\_\_  
Model No. \_\_\_\_\_  
Serial No. \_\_\_\_\_

Date installed on aircraft \_\_\_\_\_  
Time Between Overhauls (TBO) \_\_\_\_\_ Hours


If used on multi-engine aircraft:  
 Right       Left  
 Front       Rear

(All applicable information must be filled in)



**AEROTECH PUBLICATIONS INC.**  
www.adlog.com  
PO BOX 1359 / SOUTHOLD, NY 11971-0965  
(631) 765-9375  
1-800-235-6444  
FAX: (631) 765-9359

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page

N10420 Date: 6/2/03 Tach Time: 2116.3 Prop SMOH 0.0  
 Installed this prop into N10420. This prop has been inspected IAW an Annual inspection and was determined to be in airworthy condition and is approved for return to service.  
 Authorized Signature   
 Certificate #IA547175111A&P




**SULLIVAN PROPELLER SPECIALISTS**  
 20995 Skywest Drive • Hayward, California 94541  
 tel: 510.782.0920 • fax: 510.264.9162  
 FAA Repair Station S5UR963J

10-02-04    2203.3    N10420    \_\_\_\_\_  
 DATE            HOBBS/TACH            N#            RE OR LE

Add \_\_\_\_\_ grams of weight to \_\_\_\_\_  
 The location of static balance weights has been altered on propeller to correct the dynamic balance from 0.21 i.p.s to a final reading of 0.02 i.p.s. All work performed in accordance with Chadwick-Helmuth Manual No. AW9511-2 by Sullivan Propeller Specialists. Work order no. 5150 on file.

AUTHORIZED SIGNATURE 

THIS BALANCE VOID AND ALL ADDED WEIGHTS MUST BE REMOVED IF THE PROPELLER OR OTHER ROTATING MASS IS ALTERED OR CHANGED.

9-1-07	2331.1	214.8	2331.1	AD 2006-24-07 N/A NOT O/H by (SFA AVIATION)
				Date <u>9-1-07</u> Tach Time <u>2331.1</u>
				I certify that I have inspected this propeller
				in accordance with an <u>ANNOAC</u> inspection
				and found it to be in an airworthy condition.
				Total Time <u>2331.1</u> T.S.O. <u>214.8</u>
				 Ralph Huy A&P 549502281A

			<b>SUB-TOTALS</b> this page
			<b>TOTALS</b> —Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page
11-8-08	2366.3	248.0	2366.3	<p>Date <u>11-8-08</u> Tach Time <u>2366.3</u></p> <p>I certify that I have inspected this <u>Propeller</u></p> <p>in accordance with a <u>P ADPDA</u> inspection and to return it to be in an airworthy condition.</p> <p>Total Time <u>2366.3</u> T.S.O. <u>248.0</u></p> <p><u>Ralph Huy</u> Ralph Huy A &amp; P 549540228 I.A.</p>
				<p>Date: <u>6/21/2018</u> Tach: <u>2426.5</u> PTT: <u>2426.5</u> PSMOH: <u>310.2</u></p> <p>This Propeller has been inspected IAW an Annual as per FAR 43 Appendix "D". Was found to be in airworthy condition and is approved to return to service this date.</p> <p>Singed: <u>Chris Hamilton</u> Chris Hamilton 2799543 APIA Tri-Valley Aviation 925-455-5802</p>
				<p>Date: <u>8/16/2019</u> Tach: <u>2444.3</u> PTT: <u>2444.3</u> PSMOH: <u>328.0</u></p> <p>This Propeller has been inspected IAW an Annual as per FAR 43 Appendix "D". Was found to be in airworthy condition and is approved to return to service this date.</p> <p>Singed: <u>Chris Hamilton</u> Chris Hamilton 2799543 APIA Tri-Valley Aviation 925-455-5802</p>
				<p>Date: <u>9/15/2020</u> Tach: <u>2456.6</u> PTT: <u>2456.6</u> PSMOH: <u>340.00</u></p> <p>This Propeller has been inspected IAW an Annual as per FAR 43 Appendix "D". Was found to be in airworthy condition and is approved to return to service this date.</p> <p>Singed: <u>Chris Hamilton</u> Chris Hamilton 2799543 APIA Tri-Valley Aviation 925-455-5802</p>
				<p>Date: <u>11/2/2021</u> Tach: <u>2468.1</u> PTT: <u>2468.1</u> PSMOH: <u>351.5</u></p> <p>This Propeller has been inspected IAW an Annual as per FAR 43 Appendix "D". Was found to be in airworthy condition and is approved to return to service this date.</p> <p>Singed: <u>Chris Hamilton</u> Chris Hamilton 2799543 APIA Tri-Valley Aviation 925-455-5802</p>
				<p>Date: <u>2/2/2023</u> Tach: <u>2473.1</u> PTT: <u>2473.1</u> PSMOH: <u>357.1</u></p> <p>This Propeller has been inspected IAW an Annual as per FAR 43 Appendix "D". Was found to be in airworthy condition and is approved to return to service this date.</p> <p>Singed: <u>Chris Hamilton</u> Chris Hamilton 2799543 APIA Tri-Valley Aviation 925-455-5802</p>
				<p><b>SUB-TOTALS</b> this page</p>
				<p><b>TOTALS</b>—Carry forward to next page</p>