



NEW ENGLAND




PROPELLER

PROPELLER LOGBOOK

1871

1871



PROPELLER MAINTENANCE RECORD

LEFT ENGINE *McCaughey*

Hub Model B2D34C207

Blade Design G78TCA-0

Diameter \_\_\_\_\_

Hub Ser. No. 816561

Blade Ser. Nos.

No. 1 TB179

No. 2 TB180

No. 3 \_\_\_\_\_

No. 4 \_\_\_\_\_

No. 5 \_\_\_\_\_

PITCH RANGE @ *30" station*

High 27.5 Low 12.9

Feather \_\_\_\_\_ Reverse \_\_\_\_\_

Governor Model \_\_\_\_\_

RIGHT ENGINE

~~Hub Model \_\_\_\_\_~~

~~Blade Design \_\_\_\_\_~~

~~Diameter \_\_\_\_\_~~

~~Hub Ser. No. \_\_\_\_\_~~

~~Blade Ser. Nos. \_\_\_\_\_~~

~~No. 1 \_\_\_\_\_~~

~~No. 2 \_\_\_\_\_~~

~~No. 3 \_\_\_\_\_~~

~~No. 4 \_\_\_\_\_~~

~~No. 5 \_\_\_\_\_~~


PITCH RANGE

~~High \_\_\_\_\_ Low \_\_\_\_\_~~

~~Feather \_\_\_\_\_ Reverse \_\_\_\_\_~~



~~Governor Model \_\_\_\_\_~~

**DESCRIPTION OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
10-16-00	1928.	McCauley B2D34C207/G-78TCA-0	S/N 816561
		MAJOR OVERHAUL. Blades Replaced. Parts xploded, magnafluxed,	
T.S.O	00-00	Replated and Replaced as Required. Complied with Service	
		Bulletins listed on 337 Form. Propeller tracked, balanced,	
		greased, set angles and painted. Factory new blades	
		S/N's TB179 AND TB180 installed.	
		AUTHORIZED BY	REF: WO# CR-25407
		 president	
		FOR NEW ENGLAND PROPELLER SERVICE, INC.	
		EAST HADDAM, CT	
		FAA REPAIR STATION #RC2R130L	
11-20-00	1928	R&R Prop for overhaul installed in new orig check track	
			JDA# 30427.25




**DESCRIPTION OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
1-30-04	2201.45	<p>I CERTIFY THAT THIS <u>PROP</u> HAS BEEN INSPECTED I.A.W. A <u>ANNUAL</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.</p>	 AP5326848221.A.
Dress Blades, CR ups CR	TRACKING	<p>Date <u>APR 18, 06</u>            I certify that this <u>propeller</u> has been inspected in accordance with a <u>Annual</u> inspection and was determined to be in airworthy condition.            TIME <u>TACH 2275</u>            SIGNED <u>Bruce Baker</u>            LIC. # <u>AP024811051A</u>            PIONEER AVIA. CORP. TURNERS FALLS, MASS.            PHONE 413 893-9391</p>	






**DESCRIPTION OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		<b>Gardner Aviation Services Inc.</b> 499 Airport Rd. Gardner, MA 01440	
		Reg #: N1373M    Make: McAULEY 816561    Model: B2D34C207 Date: 05-17-2011    PTSMOH: 449.2    P TT: 2387.2    Tach: 2387.2	
		CW AN ANNUAL INSPECTION LAW CARDINAL RG SERIES SM CHECK LIST NO DEFECTS NOTED ALL AD'S REVIEWED AND CW TO DATE 2011-10	
		I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED LAW AN ANNUAL INSPECTION AND IS DETERMINED TO BE AIRWORTHY	
		 _____ Dominic P. Scalera APIA 2668058	

**DESCRIPTION OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		GARDNER AVIATION SERVICES INC 499 AIRPORT RD GARDNER MA 01440	PH# 978-821-2803 FAX 978-632-9876
		21 JUN 201 SN# 816561	MCCAULEY PTSM : 453.6 TT 2391.4 B2D34C207 TACH:2391.4 N1373M HOBBS:
		CW AN ANNUAL INSPECTION IAW CESSNA 177RG SERIES MM CHECK LIST NO DEFECTS NOTED ALL ADS REVIED AND ARE IN COMPLIANCE AS OF Biweekly 2012-12 NO CHANGES  I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECION AND IS DETERMINED TO BE AIRWORTHY   DOMINIC P SCALERA A&P/IA 2668058	


07/12/13    2411.17    COMPLIED WITH ANNUAL/100 Hr. Insp. of Prop I.A.W. CESSNA 177RG Service Manual. Dressed Prop and touched up flat black paint on aft. side. I certify that this prop has been inspected I.A.W. an Annual Inspection and is determined to be airworthy.  
 D. d'Alto AP 3470640 IA

J&M Aviation 467 Airport Road Middlebury, VT 05753  
LOG ID# 93 20-August-2014 WO# 103/1 AC TT 2446.5  
N1373M S/N 177RG0083 CESSNA 177RG

Pg 1/1

PROPELLER McCauley B2D34C207 S/N 816561 TSPOH 518.5

I certify this Propeller has been Inspected IAW an ANNUAL INSPECTION as outlined in Part 43 Appendix D and was determined to be in AIRWORTHY Condition.

  
Signed 2718447 Paul D Bessler Date 20-AUG-14

AIRCRAFT PROPELLER

Model Number: B2D34C207/78TCA-0 Serial Number: 816561

Work Performed: Overhauled Propeller

IAW McCauley Manuals: MPC 200 R1, SPM100 R5, BOM100 R6

Service Literature Referenced:

AD's: N/A

SB's: 119A 03/01/99

SL's: 1979-5 07/25/79, 1979-7 09/18/79, 1987-3 04/17/87, 1998-8B 03/15/01,  
2008-01 03/12/08, 2013-01 03/13/13, 2014-01A 07/21/14, 2014-01B 08/18/14,  
2014-02 09/22/14

TTSN: UNK TSO: -0-

BLADE SERIAL NUMBERS: TB179, TB180


Work Order: CTO5563

Repair Station Q0PR011X  
North Windham, CT 06256

Sensenich Propeller Service, Inc.  
Phone: 860-456-7944

Blair D Wager

Date: 03 AUG 2015



8/20/16 2494 31 SMOH  
PERFORMED A LOOK ON THIS PROP.  
AND HAVE FOUND IT TO BE AIRWORTHY

A+01546136


8/16/15 2495 31 SMOH  
PERFORMED A LOOK ON THIS PROP  
AND HAVE FOUND IT TO BE AIRWORTHY

A+P 2048103

4/16/19 I CERTIFY I HAVE INSPECTED THIS PROP IN  
ACCORDANCE WITH A LOOK + I HAVE FOUND  
IT TO BE AIRWORTHY

A+1546126

2016-144 153 SMOH  
08/17/15, TSO-0, 2463

performed annual inspection of propeller IAW 177RG MM and McCauley MM,  
Following overhaul done at Sensenich Propeller Services. All operational + leak AS  
Satisfactory. I certify that this propeller has been inspected IAW an annual insp-  
ection and determined to be in an Airworthy condition.  2740653 IA

END Log Book

**NEW ENGLAND PROPELLER SERVICE, INC.**

East Haddam Industrial Park  
East Haddam, Connecticut 06423

FAA Approved Number RC2R130L


Phone 860.873.1494 Toll Free 800.878.6377 Fax 860.873.2388




*The Standard*


# PROPELLER LOG

ASA-SP-L





MODEL SP-L



COPYRIGHT© 1987

**asa** PUBLICATIONS, INC.

6001 SIXTH AVENUE SO.  
SEATTLE, WA 98108-3307



+ Balanced

Remarks  
Overhaul  
set angles

Date	Total Time	Time Since Overhaul	Description
11-8-91	S/B S/L	110"	Overhaul C/W All Applications + Balanced - and -

Next Inspection Due: 5yr 2000 He Mech. Cert. # or Repair Station # Cent W Indiff 2311079

Date	Total Time	Time Since Overhaul	Description
12/1/91	O/H Prop		installed, torqued & safetied. TACH Time - 1767.0
Note - {old prop removed due to oil leak. Blade's & hub rejected (due to corrosion @ O/H. Sensenich recommended replacement prop)}			

Next Inspection Due: 1/93 Mech. Cert. # or Repair Station # J Smith APP # 3640985

Date	Total Time	Time Since Overhaul	Description
2-6-93	1803.19 Tach		I certify that this <u>propeller</u> has been inspected in accordance with a <u>Annual</u> inspection and was determined to be in airworthy conditions

Next Inspection Due: \_\_\_\_\_ Mech. Cert. # or Repair Station # Ed C Zell IA 372640721

# HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Date	Total Time	Time Since Overhaul	Description
3-1-94	UNKNOWN	69.3	PERFORMED 100 hr. Insp PER MCCABLY Insp. MANUAL - Funct ck - good PAINTED dressed - End - JPL Warner ANP410868364
Next Inspection Due:			Mech. Cert. # or Repair Station #

Date	Total Time	Time Since Overhaul	Description
END			Log BOOK
Next Inspection Due:			Mech. Cert. # or Repair Station #


Date	Total Time	Time Since Overhaul	Description
Next Inspection Due:			Mech. Cert. # or Repair Station #


Application

1079

0  
ated  
t pp  
7853

**MEMORANDA**









*The Standard*

# **PROPELLER LOG**

**ASA-SP-L**





*The Standard*

# **PROPELLER LOG**

**ASA-SP-L**

*The Standard Propeller Log*  
SP-L

© 1994 Aviation Supplies & Academics, Inc.

**ASA-SP-L**

ISBN 978-1-56027-418-6

All rights reserved.

Reproduction or use, without written permission,  
in any manner, is prohibited.

Published by  
Aviation Supplies & Academics, Inc.  
7005 132nd Place SE  
Newcastle, WA 98059-3153  
Website: [www.asa2fly.com](http://www.asa2fly.com)  
Email: [asa@asa2fly.com](mailto:asa@asa2fly.com)

Printed in the United States of America

19/2019

TRANSPORTATION USD \$4.95

ISBN 978-1-56027-418-6



9 781560 274186

**Propeller Record** General Information

Propeller Manufacturer Mc CAULEY

Model B2D 34C 207

Hub Series # 816561

Type \_\_\_\_\_

Blade # TB179/180

Date of Manufacture \_\_\_\_\_

Aircraft Installed On:

Make/Model

CESSNA 177 RG

Serial #

177RG0083



**HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS**

<b>Year:</b> _____	<b>Total Time in Service</b>
<b>Date:</b> _____	
<b>Next Inspection Due:</b> _____	<b>Time Since Overhaul</b>

6/15/2021      TACH: 2690.0      PTT: 2690      TSPOH: 227.0

Annual inspection to propeller.

*Mitchell Beemer*  
IA015389017

<b>Year:</b> _____	<b>Total Time in Service</b>
<b>Date:</b> _____	
<b>Next Inspection Due:</b> _____	<b>Time Since Overhaul</b>


3/10/2022      TACH: 2741.0      PTT: 2741.0      TSPOH: 278.0

Annual inspection to propeller.

*Mitchell Beemer*  
IA015389017

<b>Year:</b> _____	<b>Total Time in Service</b>
<b>Date:</b> _____	
<b>Next Inspection Due:</b> _____	<b>Time Since Overhaul</b>





LOC: 04CC P/N: 13-32370  
ASA PROPELLER LOG, SFTCVR 20 PGS



153570695 PO: 192544 : 72-18924