


S/N 832348



EAST COAST PROPELLER SERVICE INC.

PROPELLER LOGBOOK



PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model B2D34C207-B

Blade Design G78TCA-0

Diameter _____

Hub Ser. No. 832348

Blade Ser. Nos.

No. 1 DG351

No. 2 YG26387

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High 27.5° Low 12.9°

Feather — Reverse —

Governor Model _____

RIGHT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. No. _____

Blade Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____


PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

DESCRIPTION OF ALL OPERATIONS
 PERTAINING TO AIRWORTHINESS DIRECTIVES,
 SERVICE BULLETINS, SERVICE LETTERS,
 & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
1-28-08		McCawley Propeller Model B2 D34C207-B S/N 832348 was overhauled this date. See Yellow tag for details.	
MAINTENANCE RELEASE			
<p>component identified above was repaired inspected in I.A.W. regulations of the FAA is found airworthy for return to service performed. Pertinent details of the on file at this agency under work ER-6562</p>			
			 EAST COAST PROPELLER SERVICE INC. 2079 MAIN STREET LITITZ, PA 17543 FAA REPAIR STATION # E 0064Y

STA. LO: 12.90 HI: 27.5°
 REV:  FEA
 R SERVICE INC.
 Feet 243 4Y
 ECPS PROPELLER SERVICE
 and Static balanced.
 30" STAKE MAINTAINED
 set angles

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
4-23-08	2806.1	TSOH'S INSTALLED AFTER OVHL.	C. Y. Tamura ATP 243500578
12/27/14	2927.5	Inspected Prop, Spinner, and Backing Plate No defects Noted.	Barbara L Hoffman AP 3340848 IA
12/14/15	2943.8	Inspected Prop, Spinner, and backing Plate No defects noted	Barbara L Hoffman AP 3340848 IA
12/19/16	2959.0	Inspected Prop, Spinner, and Backing Plate. No defects noted.	Barbara L Hoffman AP 3340848 IA

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
N1885Q	July 10, 2021	Tach 3038.1	
		Inspected, prop, spinner and backing plate. No defects noted. I certify that this Prop has been inspected IAW a 100 Hr. Inspection and was determined to be in an airworthy condition.	

Barbara A. Huffman

Barbara A. Huffman A&P 3340848 IA



EAST COAST PROPELLER SERVICE INC.

2079 Main Street, Lititz, PA 17543
800/875-6377 • 717/627-7407 • Fax 717/627-7409

FAA Approved Repair Station: #E65RO64Y
