

MCCAULEY™


**PROPELLER
OPERATOR'S
MANUAL
&
LOG**



**MPC-10, MPC-11, MPC-12,
MPC-13, MPC-14, MPC-15,
CMM500-1**

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
11/2/15			B2D34C207-B	THIS PROPELLER WAS MANUFACTURED NEW AT McCAULEY PROPELLER SYSTEMS. INSPECTED AND FOUND TO BE AIR-WORTHY ON THIS DATE.	 (6053)
		S/N	150423		


FliteWing Inc.
503-559-6006

N2086Q
Tach: 4996.5

Date: 11/25/2015
TTAF: 4996.5

Installed this propeller using the Cessna service manual and the McCauley Owners Manual as a guide. Performed a 100 hour inspection on this propeller and found it to be airworthy. Test ran and leak checked.

Mike Ward 573944410 IA



PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
			FliteWing Inc. (503) 559-6006 SMOH: 1022.3	N2086Q Tach: 5046.0	Date: 8/17/2016 TTP: 5046.0
Performed a 100 hour inspection on this propeller using the Cessna service manual and FAR 43 appendix(d) as a guide. This propeller has been inspected in accordance with a 100 hour inspection and was determined to be airworthy.					
Mike Ward 573944410 IA					
<p style="font-size: small;">I certify that this <u>Prop</u> has been inspected in accordance with an <u>annual</u> inspection and was determined to be in <u>airworthy</u> condition.</p> <p style="font-size: small;"> Dated: <u>11/16/2017</u> Total time <u>119.6</u> hrs. <u>119.6 TTP</u> Signed: <u>[Signature]</u> <u>5116.1 TTA</u> ✓ TACA Certificate No: <u>1A 551-40-1322</u> </p>					

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
11/2/15	0	S/N	B2D34C207-B 150423	THIS PROPELLER WAS MANUFACTURED NEW AT MCCAULEY PROPELLER SYSTEMS. INSPECTED AND FOUND TO BE AIR-WORTHY ON THIS DATE.	CCF 6050

FliteWing Inc.
503-559-6006

N2086Q
Tach: 4996.5

Date: 11/25/2015
TTAF: 4996.5

Installed this propeller using the Cessna service manual and the McCauley Owners Manual as a guide. Performed a 100 hour inspection on this propeller and found it to be airworthy. Test ran and leak checked.

Mike Ward 573944410 IA

MW Ward

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number	
				<p>I certify that this <u>Prop</u> has been inspected in accordance with <u>an annual</u> inspection and was determined to be in airworthy condition.</p> <p>Dated: <u>10/4/2018</u> Total time <u>178.7</u> hrs.</p> <p>Signed: <u>[Signature]</u></p> <p>Certificate No: <u>LA557-801328</u></p>	<p>178.7 TTP</p> <p>575.2 TAct</p>	
				<p>I certify that this <u>Prop</u> has been inspected in accordance with <u>an annual</u> inspection and was determined to be in airworthy condition.</p> <p>Dated: <u>10/5/2019</u> Total time <u>223.2</u> hrs.</p> <p>Signed: <u>[Signature]</u></p> <p>Certificate No: <u>LA557-801322</u></p>	<p>TACT 5219.7</p> <p>Removed and reinstalled prop to replace ring gear. Pawl-ring A1633-11 installed</p>	

PROPELLER ASSEMBLY LOG

PAG

Quality Aero Maintenance
23987 N. Hwy. 99/P.O. Box 208
Acampo, CA PH: (209)366-1040

PROPELLER

N2086Q Date: 11/2/20 Tach: 5261.1


TT Propeller: SPOH: Date of OH:

Date

Inspect propeller, spinner and backing plate. Dress minor nicks and paint face. AD lists updated through ATP content revision 10/30/2020, none apply this date.

I certify that this propeller has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition.

Signature &
Certificate
Number


Robert R. Kempf AP5731738001A

Quality Aero Maintenance
23987 N. Hwy. 99/P.O. Box 208
Acampo, CA PH: (209)366-1040


PROPELLER

N2086Q Date: 11/19/21 Tach: 5327.1

SPOH: 330.6

Inspect propeller, spinner and backing plate. AD lists updated through ATP content revision 10/30/2020, none apply this date.

I certify that this propeller has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition.


Robert R. Kempf AP5731738001A

PAI

Quality Aero Maintenance
23987 N. Hwy. 99/P.O. Box 208
Acampo, CA PH: (209)366-1040


PROPELLER

N2086Q Date: 2/9/23 Tach: 5330.4
SPOH: 333.9

Inspect propeller, spinner and backing plate. ATP content revision 2/9/2023, none apply this date.

Da

I certify that this propeller has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition.


Robert R. Kempf AP5731738001A


Signature &
Certificate
Number

Quality Aero Maintenance
23987 N. Highway 99/P.O. Box 208
Acampo, CA 95220 PH (209) 366-1040

PROPELLER

N2086Q Date: 2/7/24 Tach reading: 5406.8 TTAF: 5406.8
SPOH: 410.3

Dynamically balance propeller @ 2500 RPM to IPS of .07, angle of 253° IAW Dyna Vibe
Classic User Manual Version 1-09


Robert R. Kempf 573173800AP

M-TH

Lodi
23987
P.O. Bo
Acampo

Mo

Groundhog Day

idents' Day (U

PAGE 1

Date

Quality Aero Maintenance
23987 N. Hwy. 99/P.O. Box 208
Acampo, CA PH: (209)366-1040

PROPELLER

N2086Q

Date: 4/2/24

Tach: 5411.2

SPOH: 414.7

Inspect propeller, spinner and backing plate. Dress minor nicks and paint face. AD lists updated through ATP content revision 3/1/2024, none apply this date.

I certify that this propeller has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition.

[Signature]
Robert R. Kempf AP573173800IA

Signature &
Certificate
Number

Quality Aero Maintenance
23987 N. Hwy. 99/P.O. Box 208
Acampo, CA PH: (209)366-1040

PROPELLER

N2086Q

Date: 8/18/25

Tach: 5460.4

SPOH: 463.9

Inspect propeller, spinner and backing plate. Dress minor. AD lists updated through VTP content revision 5/14/2025, none apply this date.

I certify that this propeller has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition.

[Signature]
Robert R. Kempf AP573173800IA

