

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
2022 10/08	0	0	Installed MT-Propeller Model MTV-9-B 3/4	Michael T Sims
			220383 per Installation Manual ATA 101-01-24	AP35674281A
			(E-124) TACH 2315.5	

N2193Q December 7, 2022 Tach 1029.3 Hobbs 2320.1 Prop Time since New 4.6 Prop installed October 28, 2022

Inspected propeller for 100 hour inspection. AD 22-18-02 "Propeller blade lag screws" is not applicable by date manufactured. I certify this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.

Greg Parker
 Greg Parker A&P 424151337
 Fayetteville Aviation, Inc.

①

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
<p>N2193Q January 16, 2024 Tach Time 1121.1 Propeller Time since new 96.4 Inspected propeller. I certify this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.</p> <p style="text-align: center;"><i>Ethan Bush</i> Ethan Bush A&P 3826710 Fayetteville Aviation, Inc.</p>				
<p>NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12</p>				

2