

FAA CRS# W59R659N

A/C N# 34077
Prop M/N B2D34C207
Prop S/N 736191

PROPELLER
LOGBOOK #1

9/25/07 — 4/8/21

PROPELLER INFORMATION

Check applicable box

Right Engine

Left Engine

Hub Model BZD34C207

Hub Serial 736191

Blade Model 78TCA-0

Blade Serial #1 B61991

Blade Serial #2 B65748

Blade Serial #3 N/A

Blade Serial #4 A

Diameter 77.4"

Governor Model _____

WARNER PROPELLER & GOVERNOR CO.

5102 S. Country Club Rd., Tucson, Az. 85706 FAA CRS # W59R659N

5746

WORK ORDER

CUSTOMER INFORMATION

BILLING

Name Jon McLin
Address 2101 E. Vaughn St
City/State/Zip Tempe, AZ 85283
Contact person Jon
Date Recieved 8/24/07

SHIPPING

Name Jon McLin
Address 2101 E. Vaughn St
City/State/Zip Tempe, AZ 85283
Phone 480-227-4109
Date promised 9/26/07

AIRCRAFT INFORMATION

A/C model Cessna 177RG Engine M/N IO-360-A1B6D

WARNER PROPELLER & GOVERNOR CO.

5102 S. Country Club Rd., Tucson, Az. 85706 FAA CRS # W59R659N

WORK ORDER

5746

CUSTOMER INFORMATION

BILLING		SHIPPING	
Name	Jon McLin	Name	Jon McLin
Address	2101 E. Vaughn St	Address	2101 E. Vaughn St
City/State/Zip	Tempe, AZ 85283	City/State/Zip	Tempe, AZ 85283
Contact person	Jon	Phone	480-227-4109
Date Recieved	8/24/07	Date promised	9/26/07

AIRCRAFT INFORMATION

A/C model	Cessna 177RG	Engine M/N	IO-360-A1B6D
A/C Serial	177RG0961	N#	34077
		Engine S/N	N/A

COMPONENT INFORMATION

Item	Propeller	Manufacturer	McCauley	Model #	B2D34C207
Serial #	768286	Part #	N/A	TTSN	Not Reported
				TTSO	Not Reported
Reason for repair	Leaking oil/over calender time TBO				
Work to be performed	Overhaul				

The customer authorizes the above repairs to be made to the above components

Customer signature _____

REQUIRED DOCUMENTS

New logbook Maintenance release CofA 337 Origin Other _____

MAINTENANCE INFORMATION

Inspection results Hub corrosion beyond limits, corrosion in blade snap ring groove S/N B61991, piston, cylinder, support, rod piston pins, and actuating pins worn beyond limits

Additional work required Rework blade snap ring groove, replace hub w/ s/n 736191, replace remaining scrap items w/ new

Parts installed 1eaC207OHK, 1ea4326/C207, 1ea 4427-1, 1ea 6911, 1ea 5263, 1ea 2345, 2ea 3414, 2ea 3905, 1ea 3418




Work performed Major overhaul and static balance

S/B, S/L, A/D compliances S/B 137AB, 227B, S/L 98-5, 98-8B, 05-08, No A/D notes apply

Maintenance release issued 8130-3 Number 26918 Date issued 9/25/07

Attatchments to this work order MM20,List,Jpac,8130-3,MM27,MM23

MAINTENANCE RECORD

Date	Time Run	T.T.S.O.	Description of all operations pertaining to A/Ds S/Bs, S/Ls, and minor adjustments	Signature
9/25/07		0.0	Major overhaul and static balance this date. Refer to WO# 5746 and 8130-3# 26918 for details and approval for return to Service.	 FAACRS# WEA R6572
9/28/07		0.0	Installed prop on C177R60961 N34077 IAW Cessna Service Manual. AF TT 3673.9 Op check	Private Pilot/owner 2828375 
9/28/07		-0-	OK. Supervised and inspected the above listed work and certify it to be correct.	 AEP 1613194

MAINTENANCE RECORD

Date	Time Run	T.T.S.O.	Description of all operations pertaining to A/Ds S/Bs, S/Ls, and minor adjustments	Signature
------	----------	----------	------------------------------------------------------------------------------------	-----------


Reg. No. - N34077

This **Propeller** has been inspected in accordance with a **Annual Inspection** and determined to be in airworthy condition at this time. Complied with Inspection checklist as per Appendix D to Part 43. For AD compliance, see recurring AD sheets and AD listing.

Date- 4/12/08

Tach	3696.4
TSP0H	22.4

Authorized Signature




A&P529664345IA

8/24/08

3727.1

53.1


Removed from airframe for engine replacement.


 PP/owner #2828375

Date
6/29/08

4/18/09

MAINTENANCE RECORD


Date	Time Run	T.T.S.O.	Description of all operations pertaining to A/Ds S/Bs, S/Ls, and minor adjustments	Signature
6/29/09	3722.1	53.1	Reinstalled an airframe 177R60961 after engine replacement.	 PP/aww #2828375
7/18/09			Supervised and inspected the above listed work and certify to be airworthy. E.A. Hammett, A&P 1613194	

Reg. No. N34077

This **Propeller** has been inspected in accordance with a **Annual Inspection** and determined to be in airworthy condition at this time. Complied with Inspection checklist as per Appendix D to Part 43. For AD compliance, see recurring AD sheets and AD listing.

Date- 7/18/09 ^{da}

Tach	3727.1
TSPOH	53.1

Authorized Signature 

A&P5296643451A

MAINTENANCE RECORD

Date Time Run T.T.S.O. Description of all operations pertaining to A/Ds S/Bs, S/Ls, and minor adjustments Signature


Reg. No. N34077

Date- 9/11/10

This **Propeller** has been inspected in accordance with a **Annual Inspection** and determined to be in airworthy condition at this time. Complied with Inspection checklist as per Appendix D to Part 43. For AD compliance, see recurring AD sheets and AD listing.

Tach	3772.1
TSPOH	98.1

Authorized Signature


A&P529664345IA


Reg. No. N34077

Date- 10/8/11

This **Propeller** has been inspected in accordance with a **Annual Inspection** and determined to be in airworthy condition at this time. Complied with Inspection checklist as per Appendix D to Part 43. For AD compliance, see recurring AD sheets and AD listing.

Tach	3834.2
TSPOH	160.2

Authorized Signature


A&P529664345IA

MAINTENANCE RECORD

Date Time Run T.T.S.O. Description of all operations pertaining to A/Ds S/Bs, S/Ls, and minor adjustments Signature

Reg. No. N34077

This **Propeller** has been inspected in accordance with a **Annual Inspection** and determined to be in airworthy condition at this time. Complied with Inspection checklist as per Appendix D to Part 43. For AD compliance, see recurring AD sheets and AD listing.

Date- 10/13/12

Tach	3844.6
TSPOH	117.5

Authorized Signature

[Signature]
A&P21456131A

Reg. No. N34077

This **Propeller** has been inspected in accordance with a **Annual Inspection** and determined to be in airworthy condition at this time. Complied with Inspection checklist as per Appendix D to Part 43. For AD compliance, see recurring AD sheets and AD listing.

Date- 11/4/13

Tach	3917.6
TSPOH	190.5

Authorized Signature

[Signature]
A&P21456131A


MAINTENANCE RECORD

Date	Time Run	T.T.S.O.	Description of all operations pertaining to A/Ds S/Bs, S/Ls, and minor adjustments	Signature	Date
------	----------	----------	------------------------------------------------------------------------------------	-----------	------


Reg. No. N34077 McCauley B2D34C207 S/N 736191
Date- 6/20/15


This **Propeller** has been inspected in accordance with a **Annual Inspection** and determined to be in airworthy condition at this time. Complied with Inspection checklist as per Appendix D to Part 43. For AD compliance, see recurring AD sheets and AD listing.

Tach	3975.3
TSPOH	305.9

Authorized Signature 
A&P2145613IA

01 SEP 2016
 TTSN 4015.1 TTSO 341.2
 Resealed, functional tested and static balanced. Refer to work order # 12202 and 8130-3 # 36671.


 Brooke Warner
 Warner Propeller Tucson, AZ
 FAA CRS# W59R659N




Reg. No. N34077 McCauley B2D34C207 S/N 736191

Date- 10/1/16

This **Propeller** has been inspected in accordance with a **Annual Inspection** and determined to be in airworthy condition at this time. Complied with Inspection checklist as per Appendix D to Part 43. For AD compliance, see recurring AD sheets and AD listing.

Tach	4015.1
TSP0H	345.7

Flight Sport Aviation, LLC
Anthony Bell A&P, IA



Authorized Signature

A handwritten signature in black ink, appearing to be 'Anthony Bell', written over a horizontal line.

A&P2145613IA


Reg. No. N34077 McCauley B2D34C207 S/N 736191

Date- 10/13/17

This **Propeller** has been inspected in accordance with a **Annual Inspection** and determined to be in airworthy condition at this time. Complied with Inspection checklist as per Appendix D to Part 43. For AD compliance, see recurring AD sheets and AD listing.

Tach	4060.2
TSP0H	390.8

Flight Sport Aviation, LLC
Anthony Bell A&P, IA



Authorized Signature

A handwritten signature in black ink, appearing to be 'Anthony Bell', written over a horizontal line.

A&P2145613IA

MAINTENANCE RECORD

Time

Description of all operations pertaining to


Reg. No. N34077 McCauley B2D34C207 S/N 736191

Date- 11/9/18

This **Propeller** has been inspected in accordance with a **Annual Inspection** and determined to be in airworthy condition at this time. Complied with Inspection checklist as per Appendix D to Part 43. For AD compliance, see recurring AD sheets and AD listing.

Tach	4082.9
TSPOH	413.5

Flight Sport Aviation, LLC
Anthony Bell A&P, IA



Authorized Signature

Anthony Bell
A&P2145613IA

Signature


Reg. No. N34077 McCauley B2D34C207 S/N 736191

Date- 3/26/20

This **Propeller** has been inspected in accordance with a **Annual Inspection** and determined to be in airworthy condition at this time. Complied with Inspection checklist as per Appendix D to Part 43. For AD compliance, see recurring AD sheets and AD listing.


Tach	4090.3
TSPOH	420.9

Flight Sport Aviation, LLC
Anthony Bell A&P, IA



Authorized Signature

Anthony Bell
A&P2145613IA



5102 S. Country Club Rd. Tucson, AZ 85706
www.warnerpropeller.com

FAA CRS # W59R659N
(520) 294-5671

WORK ORDER #

12202

WORK ORDER

CUSTOMER/ AIRCRAFT INFORMATION

CUSTOMER

Name Jon McLin
Address 2101 E. Vaughn St.
City/State/Zip Tempe, AZ 85283
Contact person Jon McLin
Phone 480-227-4109


AIRCRAFT

Aircraft model Cessna 177RG
Aircraft serial N/A
Engine model IO-360-A1B6D
Registration N34077
Date received 02 AUG 2016

COMPONENT INFORMATION

Component(s) Propeller

Manufacturer McCaughey



5102 S. Country Club Rd. Tucson, AZ 85706
www.warnerpropeller.com

FAA CRS # W59R659N
(520) 294-6671

WORK ORDER #
12202

WORK ORDER

CUSTOMER/ AIRCRAFT INFORMATION

CUSTOMER

Name Jon McLin
Address 2101 E. Vaughn St.
City/State/Zip Tempe, AZ 85283
Contact person Jon McLin
Phone 480-227-4109

AIRCRAFT

Aircraft model Cessna 177RG
Aircraft serial N/A
Engine model IO-360-A1B6D
Registration N34077
Date received 02 AUG 2016

COMPONENT INFORMATION

Component(s) Propeller
Model(s)/Part(s) B2D34C207
Serial(s) 736191
Reason for repair Blades leak grease.
Work to be performed Repair as required.

Manufacturer McCauley
TTSN 4015.1
TTSO 341.2

MAINTENANCE INFORMATION

Inspection results Grease leaking from blades. Blade bearing races loose.

Additional work required Reseal propeller. Modify blades to "G" and change blade MN to G78TCA-O. Restamp hub MN with "B" to indicate bearing change. Hub MN now B2D34C207-B. Replace blade bearing races with new oversize bearing races.

Parts installed 1ea C207RSK, 2ea C7233.

Work performed Resealed, functional tested and static balanced.

S/B,S/L,A/D compliances SL 1995-19.

Maintenance release issued 8130-3 Number 36671 Date 01 SEP 2016

Attachments to this work order MM20,MM27,Jpac,List,8130-3.



Warner Propeller & Governor Co.

Mailing: P.O. Box 11278

Tucson, Az. 85734-1278

Shipping: 5102 S. Country Club Rd.

Tucson, Az. 85706

Telephone: (520) 294-5671 Fax (520) 294-1114

FAA CRS# W59R659N