

Propeller Logbook



SENENICH PROPELLER SERVICE, INC.



- McCauley
- Hartzell
- MT
- Sensenich
- Dowty
- Hamilton Standard

INSTALLING AGENCY PLEASE NOTE:
Recording of Propeller Total Time Since New (TTSN)
is Required Per E.A.R. 91.417



787813

Lancaster Airport, 519 East Airport Road, Lititz, PA 17543 (800) 462-3412 (717) 560-3711 Fax: (717) 560-4354 FAA Certified Repair Station #QV9R194N
Lee Gilmer Memorial Airport, 1142 Aviation Boulevard, Gainesville, GA 30501 (800) 791-7767 (770) 538-0444 Fax: (770) 538-0117 FAA Certified Repair Station #S46R346N
Windham County Airport, 21 Airport Road, North Windham, CT 06256 (877) 456-7944 (860) 456-7944 Fax: (860) 456-0410 FAA Certified Repair Station #Q0PR011X


SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
			<p>I certify that this <u>Prop</u> has been inspected in accordance with an <u>A&P</u> inspection and determined to be in airworthy condition</p> <p><i>[Signature]</i> A&P 3168454</p>	
1/2010			<p>I certify that this <u>Propeller</u> has been inspected in accordance with an <u>100 hr</u> inspection and determined to be in airworthy condition</p> <p><i>[Signature]</i> A&P 254307</p>	

SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
10 Feb 11	Tach 3237.1	I certify that this propeller has been inspected in accordance with an <u>Annual</u> inspection and determined to be in airworthy condition.	 <p>KRUQ- Rowan County Airport 3680 Airport Loop Rd Salisbury, NC 28147 (704) 310-1421</p> <p>N #: 34150</p> <p>Make: McCauley Date: January 25, 2013</p> <p>Model: 2D34C202</p> <p>S/N: 715193 (hub) Tach/Hobbs: 3254.4</p> <p>Performed an Annual Inspection of this aircraft propeller referencing Cessna 177B Series Maintenance Manual Inspection Guide.</p> <p>Removed propeller to replace O-ring in prop hub and prop seal P/N MS28775-228 & LW13792.</p> <p>Search of all applicable AD's shows in compliance to date.</p> <p>I certify that this propeller has been inspected in accordance with an Annual Inspection and is approved for return to service at this time.</p> <p>Stephen B. Beckham AP/IA 3640025 </p>	<p>ARP 3168854</p>

SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
7 APR 2015	ADDRESSED	PROP BLADES	5 - CLEANED and PAINTED BLADE FACES	
		TACH: 3404.6		
		PROP SMOHT: 213.6		
<p>SENENICH PROPELLER SERVICE, INC.</p> <p>DATE: 7-16-15 CRS: QV9R194N</p> <p>Hub Model: 3436-2 A/C Reg: N34150</p> <p>Propeller TTSN: 32234C208 Hub S/N: 787815</p> <p>Propeller TTSO: _____</p>				
<p>Summary of work performed</p> <p>Removed & reinstalled Propeller IMW. McCauley approved data. Gps & leak checked good. Dynamic balanced Propeller to .02 IPS IMW Chadwick Helmholtz Smooth Propeller II, & McCauley Service Letter 1989-4D. - End -</p>				
<p>Date: <u>7 APR 2015</u> Prop</p> <p>I certify that this aircraft engine</p> <p>has been inspected in accordance with <input checked="" type="checkbox"/></p> <p>AMJAL inspection and was determined</p> <p>to be in airworthy condition</p> <p>Total time <u>213.6</u> tach time <u>3404.6</u></p> <p>SINCE OH</p> <p style="text-align: center;"> IA 114427782</p>				
<p>Pertinent details of this repair or overhaul are on file at this repair station under work order # <u>126843</u></p> <p>Signed <u>Mark D. Fisher</u> for Sensenich Propeller Service, Inc., 519 E. Airport Rd. Lititz, PA 17543</p> <p>This signature constitutes approval for return to service of this aircraft ONLY FOR THE WORK WE HAVE PERFORMED.</p> <p>We have not performed nor been authorized to perform any inspection of this aircraft nor have we reviewed or been authorized to review the maintenance records, including Part 39 compliance.</p>				

