

HARTZELL PROPELLER INC.
One Propeller Place
Piqua, Ohio 45356-2634 U.S.A.
Telephone: 937.778.4200
Telex: 4332032
Fax: 937.778.4391

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-C3YR-1RF/F7282

PROPELLER S/N PA259B

N51386

LOGBOOK # 1

Model Number HC-C3YR-1RF/F7282											
Ass'y Ser No. PA259B		Hydr Unit No. NA		Bulkhead No. NA		Valve No. NA					
Blade 1: L16975		Blade 2: L16977		Blade 3: L16978		Blade 4:		Blade 5:		Blade 6:	
Clamp 1:		Clamp 2:		Clamp 3:		Clamp 4:		Clamp 5:			
Reverse NA	Start Lock NA	Low Pitch 12.5	High Pitch 30.0	Feather NA	Position 3	Orient. L	Qty:Al 0	St 1	Scrw 0	A-2424-1 0	Washer 0
Ref Radius (inches) for angles: 30											
Comments: Deice Kit: NA											
Packing Certified By: <i>[Signature]</i>				Date: 10-25-11							
Inspected By: Tim Jess											

The approved design data for this propeller incorporates all changes required by applicable Airworthiness Directives.

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE

Propeller Model HC-C3YR-1RF/F7282

High/Feather 30.0

Propeller S/N PA 259B

Start Lock N/A

Blade Design _____

Low 12.5

Blade S/N's

Reverse N/A

No. 1 L 16975

Aircraft Manufacturer Cessna

No. 2 L 16977

Aircraft Model C177RG

No. 3 L 16978

S/N 177RG 1138

No. 4 _____

Registration N51386

No. 5 _____

No. 6 _____

Spinner Assembly Part No. C-4583-2P *€ (sticker on backing plate)*

Date	Propeller TSN	TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
				Pro-Flight Aviation, Inc. 750 W. Perimeter Rd. Renton, WA 98057
12/14/2011	N51386	2805.5	Tach 6409.2 ACTT 0.0 TTP (New)	This propeller s/n PA259B and new spinner assembly installed on Cessna s/n 177RG1138 (N51386) per Hartzell manual 115N, IAW STC SA1556GL (previously approved 3/1995). Post installation run up, leak and function checks all normal. <u>Annual Inspection</u> c/w this date.
				<i>C.D. Edwards</i> Chris Edwards A&P 3461422 IA
				Pro-Flight Aviation, Inc. 750 W. Perimeter Rd. Renton, WA 98057
August 17, 2012	Cessna 177RG	N51386	09.5 Tach 6508.5 ACTT 99.3 TTP	Annual Inspection and Maintenance performed per Hartzell Manual 115N and Cessna SM.
				<i>C.D. Edwards</i> Chris Edwards A&P 3461422 IA

2/14/13	198.3	TTP	TACH 108.5	100 hr inspection + Maint. A+P 3552852 R.Hgby
3/14/14	TACH 203.9	TTP	TTP 293.6	Annual Inspection and MTX c/w C.D. Edwards 3461422 IA
10/17/14	300.0		390.4	" " A+P 3552852 R.Hgby
10/12/15	399.1		489.5	ANNUAL INSP + MAINT BAPchick A+P 468781561 IA
8/12/16	497.0		587.4	ANNUAL INSP + MAINT BAPchick A+P 468781561
9/29/17	TACH 556.3		TTP 646.7	ANNUAL INSPECTION + MAINT. Cam-home IA 3503376
10/1/18	560.6		651.0	ANNUAL INSP + MAINT BAPchick A+P 468781561 IA
11/1/19	606.1		TTP 696.5	ANNUAL INSP + MAINT R.Hgby A+P 3552852 IA
12/29/20	668.3		TTP 758.7	ANNUAL INSP + MAINT BAPchick A+P 468781561 IA
7/2/21	763.9		TTP 854.3	ANNUAL INSP + MAINT BAPchick A+P 468781561 IA
7/29/22	864.2		TTP 954.6	ANNUAL INSP + MAINT R.Hgby A+P 3552852 IA
12/1/23	963.8		1053.2	ANNUAL INSP + MAINT. BAPchick A+P 468781561 IA

HARTZELL PROPELLER INC.

One Propeller Place

Piqua, Ohio 45356-2634 U.S.A.

Telephone: 937.778.4200

Telex: 4332032

Fax: 937.778.4391