





PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
12/8/14	0	0	B2D34C211-B 140663	THIS PROPELLER WAS MANUFACTURED NEW AT McCAULEY PROPELLER SYSTEMS. INSPECTED AND FOUND TO BE AIR WORTHY ON THIS DATE	 6050
12-26-14	0	0	N1479C	Tach: 2833.9 This propeller installed in this aircraft 12-26-14 at tach time 2833.9. Function test normal. —	 AP3683725
02-01 2021	279.2	"	N1479C	Tach: 3113.1 Inspected Prop. in Ref. to 100 hr list & found Airworthy	 344491

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
				DATE: 12-18-15 N#: 1479C TACH: 2871.8 AFTT: 2871.8 TSN: 37.9	
	ALL ADS C/W AND UP TO DATE. I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION PER FAR PART 43 APP (D) AND WAS FOUND AIRWORTHY. CHARLES LITTON AP 3683725 <i>Charles Litton</i>				
	12-18-15 TACH: 2871.8 TSN: 37.9 I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION PER FAR PART 43 APP(D) AND WAS FOUND AIRWORTHY <i>Jack R. Halliday IA 2877061</i>				



PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number



FOX FIELD
4555 W. AVE. G
LANCASTER, CA. 93536
USA (661)948-2048

DATE:12-9-16
N#1479C
TACH:2888.3
AFTT:2888.3
TSN:54.4

ALL ADS C/W AND UP TO DATE.
I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH
A 100 HOUR INSPECTION PER FAR PART 43 APP. (D) AND WAS FOUND AIRWORTHY.
CHARLES LITTON AP 3683725

Charles Litton

12-9-16 TACH:2888.3 TSN:54.4
I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL
INSPECTION PER FAR PART 43 APP(D) AND WAS FOUND AIRWORTHY.

Jack D. Halliday IH 2074061


PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
10-9-17	111.2	111.2		I HAVE INSPECTED THIS PROPELLER IAW AN ANNUAL INSPECTION AND FIND IT TO BE IN AN AIRWORTHY CONDITION. REF. FAR PART 43 APPENDIX D. Bul. Polk 2188149 A-P 1A	

Twin Oaks Aircraft Maintenance, LLC Daniel W Stark 12405 SW River Road Hillsboro, OR. 97123 danny@twinoaksaircraft.com Tach: 3030.9 & PTSMOH: 197	11/8/2018 Cessna 177B Lycoming O-360-A1F6D McCauley B2D34C211	N1479C S/N: 17702735 S/N: L-24370-36A S/N: 140663
--	--	--

Completed annual inspection per service manual and FAR 43 appendix D. I certify this propeller has been inspected IAW an annual inspection and was determined to be in airworthy condition.


Daniel W Stark 2708377 IA

11-18-2019	239.2	239.2	N1479C	Inspected propeller IAW an 100hr inspection. Dustin Wine A&P #344491	
------------	-------	-------	--------	--	--

