



Single Engine  
**MANDATORY**

# ATTACHMENT

## CARRY-THRU SPAR INSPECTION REPORT

Page: 1 of \_\_ Pages

Includes this cover sheet

To:  
 Wichita Citation Service Center  
 Attn: Textron Aviation Team Structures  
 2121 S. Hoover Rd  
 Wichita, Kansas 67209  
 Phone Number: 316-517-6061  
 email: structures@txtav.com

Registration No.: N29673  
 Total Time in Service (Hrs.): 3726.08

From:  
 Date: 22/FEB/2024  
 Airplane Serial Number: 17701018  
 Owner's Name: Fred Burnett  
 Owner's Address:  
 119 Pleasant Valley Rd W  
 Greenbrier, AR 72058  
 Owner's Phone Number: (501) 679-4410  
 Owner's Fax Number:

Facility Name:  
 Facility Address:  
 Phone Number of Facility:  
 Fax Number of Facility:

Please provide detailed and dimensioned descriptions of any crack(s) or corrosion. Attach pictures to this form as necessary.

Comments/Notes:	Cracks: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> (Circle One)
Eddy Current Inspection No Rejectable Defects Noted	Corrosion: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> (Circle One)
See Attached Certificate of Conformance	Airplane Operation:
Aircraft Structural Inspections FAA CRS	Severe: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> (Circle One)
#1NPR910B ASI WO# 6902	Typical: <input checked="" type="checkbox"/> Yes No (Circle One)
	Unknown: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> (Circle One)

Any previously known or recorded blending or material removal on the carry-thru spar? Yes  No  (Circle One)

List any Structural Supplemental Type Certificates (STC's) Installed: