

Owner Name _____

Address _____

Propeller Model B2D34C207-B

Blade Model G-78TCA-0

Hub Serial No. 022317



Blade Serial No. 1 XE26120

2 XE26124

3 _____

4 _____

INSTALLATION HISTORY

Date	Aircraft Model & Registration Number	Engine Serial Number & Position
6-04-03	THIS PROPELLER WAS MANUFACTURED NEW AT MCCAULEY PROPELLER SYSTEMS, INSPECTED AND FOUND TO BE AIRWORTHY ON THIS DATE.	
6-20-03	INSTALLED Prop on	ENG S/N RL 15547-51A
3904.7 TASH	CESSNA 177RB S/N 177RG0788	
7-20-04	INSPECTED PROPELLER IAW ANNUAL INSP FOUND AIRWORTHY	

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
06/15/09 TACH 3991.8	87.4 TSN		I certify that this Propeller has been inspected IAW an annual inspection and was found to be in airworthy condition.	Edward D VanRath IA 357465746
8/5/2010 TACH 3992.4	88.2 TSN		this is to certify that this Propeller has been inspected IAW an annual inspection and was found to be in airworthy condition.	Robert Connor IA 2681097
03/12/2012 TACH 4010.1	105.7 TT		I certify that this propeller has been inspected IAW an annual inspection and was found to be in airworthy condition.	Edward D VanRath IA 3502862

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY


Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
05/01 2016	120.3		This date I certify that this propeller has been	
TACH 4024.7	inspected	IAW a annual inspection and was found to be in	current condition. IA 3502862 Edward D VanLoth Ed VanLoth	
02-15 2019	120.4		This date I certify that this propeller has been	
TACH 4024.8	inspected	IAW a annual inspection and was found	to be in current condition Edward D VanLoth IA 3502862	

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

Aviation Plus LLC
262-656-1260
Aviationplusllc.com

01/24/2020 N700CD Tach 4061 TTP 157


All routine items checked per inspection sheets. FAR 43 App D. I certify that this propeller was inspected in accordance with an annual inspection and was determined to be in airworthy condition.


Robert Russell 3411885IA

Aviation Plus Services LLC
262-656-1260
Aviationplusllc.com

02/19/2021 N700CD Tach 4100 TTP 196


All routine items checked per inspection sheets. FAR 43 App D. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.


Robert Russell 3411885 IA

Aviation Plus LLC
262-656-1260
Aviationplusllc.com

04/01/2022 N700CD Tach 4125 TTP 221

All routine items checked per inspection sheets. FAR43 App D. I certify that this propeller was inspected in accordance with an annual and was determined to be in airworthy condition.


Robert Russell 3411885IA

Date

Note

res
ion
rs


2

Aviation Plus LLC
262-656-1260
Aviationplusllc.com

06/12/2023 N700CD Tach 4149 TTP 245

All routine items checked per inspection sheets. FAR 43 APP D. I certify that this propeller was inspected in accordance with an annual inspection and was determined to be in airworthy condition.

Da


Robert Russell 3411885IA

Inspection
Items

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12