

NT574V



McCAULEY™

PROPELLER LOGBOOK

McCauley Propeller Warranty Policy

Dear Customer,

Congratulations on the purchase of your new McCauley propeller. Engineered with the customer in mind, it is designed to provide years of reliable and trouble-free service.

Scheduled maintenance or servicing of your McCauley propeller should be accomplished at your nearest McCauley Approved Service Station.

For location of the McCauley Approved Service Station nearest you, please call 1-316-831-4021 and ask for Product Support.

NOTE

Having work performed at a facility other than a McCauley Approved Service Station may void your warranty.

USE OF LOGBOOK

1. Proper maintenance of this logbook is the owner's responsibility. It is an important record designed for the owner's information and protection.
2. If the propeller is sold or installed on another aircraft, the logbook should be transferred with the propeller.
3. It is recommended that maintenance release tags and work orders be attached inside the back cover of this book. If a copy of the work order is not available, the repair station and work order numbers should be referenced in the logbook entry.
4. All Airworthiness Directives, Service Bulletins, and Service Letters have been complied with at the time of production.

CONTENTS

Installation History

Service History

AD's, Service Bulletins

Maintenance Release Tags

Owner Name _____

Address _____

Propeller Model B2D34C207-B

Blade Model G-78TCA-0

Hub Serial No. 071350

Blade Serial No. 1 ABH26310

2 ABH26311

3 _____

4 _____

INSTALLATION HISTORY

Date	Aircraft Model & Registration Number	Engine Serial Number & Position
SEP 20 2007	THIS PROPELLER WAS MANUFACTURED NEW AT MCCAULEY PROPELLER SYSTEMS, INSPECTED AND FOUND TO BE AIRWORTHY ON THIS DATE.	
		IC 6007

Mid Atlantic Aviation Inc.

Williamsburg, VA

April 01, 2009

Aircraft: C-177


N #: 7574V

Tach: 3723.0

Installed Propeller onto Airframe N7574V. Performed a 100 hour inspection I/A/W CFR Title 14 Part 43 Appendix D Inspection Checklist. I certify this prop has been inspected I/A/W a 100 hour inspection and was determined to be in airworthy condition at this time.

Kevin Steele

AP2706053



www.midatlanticaviation.com

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
3/4/10	77.8	3800.8	Filed, Painted & Inspected	
			Prop. Lubrication	AT/18/2061
4/2/11	199.2	3923.2	Filed, Painted & Inspected	
			Prop. Lubrication	AT/18/4006
5/14/14	384.2	4112.2	Filed, Painted & Inspected	
			Prop. Lubrication	AT/18/4006
5/8/15	473.5	4196.5	Cleaned, Painted & Inspected	
			Prop. Lubrication	AT/18/4006

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
3/4/16	530.9	4253.9	Cleaned, Painted & Insp Prop	Robert Chen AT-PB4006
3/5/16	591.4	4314.4	Cleaned, Painted & Insp Prop	Robert Chen AT-PB4006
3/4/18	680.3	4342.8	Cleaned, Painted & Insp Prop	Robert Chen AT-PB4006
5/11/19	715.1	4377.6	Cleaned, Painted & Insp Prop	Robert Chen AT-PB4006

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time / Hours	Time / Hours	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
4/22/20	734.4	4396.9	Cleaned, Painted & Inspected Prop. Time 4/22/2006	
10/24/21	746.8	4409.3	Cleaned Painted & Inspected Propeller Time 4/22/2006	
	758.3	4420.8	Cleaned & Inspected Propeller Time 4/22/2006	

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12




ARLIN'S AIRCRAFT SERVICE, INC.

200 Wings Way, Belgrade, MT 59714 (406)-898-2012
CRS QM5R150N (KBZN)

DATE	REGISTRATION	PROPELLER	SERIAL #	TAC	SPNEW
7 DEC 2022	N7574V	B2D34C207B	071350	4420.8	697.8

Cleaned and inspected propeller. I certify that this propeller has been inspected in accordance with a 100HR inspection and was determined to be in an airworthy condition.


Arlin C. Wass A&P 1340061




ARLIN'S AIRCRAFT SERVICE, INC.

200 Wings Way, Belgrade, MT 59714 (406)-898-2012
CRS QM5R150N (KBZN)

DATE	REGISTRATION	PROPELLER	SERIAL #	TAC	TSNEW
15 JAN 2024	N7574V	B2D34C207B	071350	4434.0	711.0

Cleaned and inspected propeller. I certify that this propeller has been inspected in accordance with a 100HR inspection and was determined to be in an airworthy condition.


Alan C. Wass A&P 2386273

HISTORY

Authorized S
Repairman a
Certificate M

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pa



**ARLIN'S AIRCRAFT
SERVICE, INC.**

200 Wings Way, Belgrade, MT 59714 (406)-898-2012
CRS QM5R150N (KBZN)

DATE	REGISTRATION	PROPELLER	SERIAL #	TAC	SPNEW
1 NOV 2024	N7574V	B2D34C207B	071350	4470.1	747.1

Cleaned and inspected propeller. I certify that this propeller has been inspected in accordance with a 100HR inspection and was determined to be in an airworthy condition

Don Carson

Alan C. Wass A&P 2386273

E HIST

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers

Service Bulletins On Pages 11 & 12

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MPC-10
NOVEMBER 2001